

EEPC2003 ELECTRICAL MACHINES-II (3-0-0)

SYLLABUS

Module I (08 Hours)

Three-phase synchronous generators:

Construction, Salient pole type and Cylindrical rotor structure, Armature windings, Winding factor, EMF equation, Armature reaction, Synchronous impedance, Alternator on load, Phasor diagrams, Open Circuit and Short Circuit tests, Short Circuit Ratio, Voltage regulation by EMF, MMF and ZPF methods, Two reactance concept of Salient pole Synchronous machines, Slip test, Power equations, Power angle characteristics.

Module II (06 Hours)

Parallel operation of alternators:

Requirements for parallel operation, synchronizing of alternators, three dark lamp method, synchroscope, synchronizing current, synchronizing power, synchronizing torque, effect of increasing the excitation, effect of increasing the driving torque and effect of change in speed of one of the alternators, load sharing between two alternators.

Module III (04 Hours)

Synchronous motors: Rotating magnetic field, operating principle of a synchronous motor, phasor diagrams, power equations, load angle, 'V' and inverted 'V' curves, synchronous condenser, starting methods, hunting.

Module IV (06 Hours)

Three-phase induction motors: Construction, principle of operation, types, squirrel cage rotor, slip ring induction motor, slip, torque equations, starting torque, full load torque, maximum torque, torque-slip and torque-speed characteristics, effect of rotor resistance, effect of change in supply voltage, effect of change in frequency, power losses and efficiency, synchronous watt, equivalent circuit of induction motor, phasor diagrams, power output, testing of induction motors, No-load test, Blocked rotor test, load test, measurement of slip, circle diagram.

Module V (06 Hours)

Starting and speed control of three-phase induction motors: DOL starting, stator resistance starting, auto transformer starting, star-delta starting, starting of slip ring induction motors, speed control by variation of supply voltage-supply frequency, rotor resistance control, crawling and cogging effects.

Single-phase induction motors: Construction, principle of operation, double field revolving theory, equivalent circuit, performance characteristics, starting methods, capacitor start-capacitor run single phase induction motors.

A.C. Generator

①

Difference betⁿ D.C. generator & Alternator:-

It is seen that in case of d.c. generator, basically the nature of Induced emf in armature conductor is alternating type and by the help of commutator we convert it to d.c..

If commutator is removed from d.c. generator and induced emf is tapped from armature directly, then the nature of such emf will be alternating. "such a machine without commutator, providing an a.c. emf to external ckt is called alternator".

We know that induced emf is basically the effect of the relative motion present betⁿ the armature and field. So in case of d.c. generator the relative motion is achieved by rotating the armature with constant field. But in case of alternator it is possible to have.

- i) Rotating armature & stationary field.
- ii) Rotating field & stationary armature.

Key-point:- Practically most of the ~~armature~~ alternators prefer rotating field type construction due to certain advantages.

Advantages of Rotating field over Rotating Armature:-


- * As everywhere a.c. is used, the generation level of a.c. voltage is high as 11 kV to 23 kV. This sets induced in the armature. For stationary armature large space can be provided to accommodate large number of conductor and the insulation.

- * To avoid electrical and mechanical stresses it is always better to protect high voltage wdg from centrifugal force caused due to rotation. Hence it is better to keep stationary armature.
- * It is easier to collect large current at very high voltage from a stationary member.
- * Due to low voltage level on field side, the insulation required is less hence field system has very low inertia. So it is better to rotate low inertia system than high inertia. as efforts required is less.
- * The ventilation arrangement for high voltage side can be improved if it is kept stationary.

Construction:-

In alternator the stationary winding is stator while rotating winding is rotor.

- * So most of the alternators have stator as armature and rotor as field, in practice.



The stator is a stationary armature. It consists of a core and the slots to hold the armature wdg. Similar to the armature of a d.c. generator, the stator core uses a laminated construction, to reduce eddy current and hysteresis loss.

(2)


frame does not carry any flux and serves as the support to the core. Ventilation is maintained with the help of holes in the frame.

Rotor:-

There are two types of rotor in alternator.

- i) Salient Pole type.
- ii) Smooth cylindrical type.


i) Salient pole type Rotor: → field wdg.




This is also called Projected Pole type as ~~all~~ all the poles are projected out from the surface of the rotor.

The poles are built up of thick steel lamination. The poles are bolted to the rotor. The pole faces are a specific shape. The field winding is provided, on the pole shoe.

These rotor have large diameter and small axial length. As the mechanical strength of the pole is less this is preferred for low speed alternator ranging from 125 r.p.m to 500 r.p.m. The prime mover preferred for low speed alternator to drive such rotor are generally water turbine.




ii) Smooth cylindrical type rotor.



This is also called non salient type or non-projected pole type rotor.

The rotor consists of smooth solid steel cylinder, having number of slots to accommodate the field coil. The unslotted portions of the cylinder itself act as the poles. The poles are not projecting out and the surface of the rotor is smooth which maintain uniform air gap betⁿ stator and the rotor. These rotor have small diameter and large axial length. The main advantages of this type is that these are mechanically very strong and thus preferred for high speed alternator ranging betⁿ 1500 to 3000 r.p.m. such high speed alternator is called turbo-alternator. The prime mover used to drive such type of rotor are generally steam turbine, electric motors.



(Sectional view)

③

Difference betⁿ Salient & non-salient Pole type rotor

Salient pole

- * Poles are projecting out from the surface
- * Air-gap is non-uniform
- * Diameter is high & short axial length
- * Mechanically weak
- * Preferred for low speed
- * Prime mover used are water turbine, I.C. engine
- * Separate Damper wdg will be provided

Non-Salient pole

- * Poles are non projecting & unsloped portion acts as poles.
- * Air-gap is uniform.
- * Small Diameter & large axial length.
- * Mechanically strong.
- * Preferred for high speed.
- * Prime mover used are steam turbine, electric motor.
- * Separate Damper wdg is not necessary.

Note:-

Working Principle of alternator is same as D.C. generator

EMF Equation of an alternator:

Let ϕ = flux per pole in wb.

P = Number of poles.

N_s = Synchronous speed in r.p.m.

f = frequency of induced emf in Hz.

Z = total no. of conductor.

Z_{ph} = conductor per phase connected in series

$$\therefore Z_{ph} = \frac{Z}{3} \quad (\text{as no. of Phases} = 3)$$

Consider a single conductor placed in a slot.

Average value of emf induced in a conductor.

$$= \frac{d\phi}{dt}$$

for one revolution

Total flux cut by conductor = $\phi \times P$.

\therefore time taken for one revolution = $\frac{60}{N_s}$.

$$\therefore \text{Eavg per conductor} = \frac{\phi P}{\left(\frac{60}{N_s}\right)} = \frac{\phi P N_s}{60} \quad \text{--- (1)}$$

But we know that $f = \frac{P N_s}{120}$.

$$\therefore \frac{P N_s}{60} = 2f$$


So equation (1) will be

$$\text{Eavg per conductor} = 2f \phi \text{ volt.}$$

④

Assuming full pitch winding for simplicity i.e. this conductor is connected to a conductor which is 180° electrical apart. so these two emf will try to set up a current in the same direction i.e. the two emf are helping each other and hence resultant emf per turn will be twice the emf induced in a conductor.

$$\begin{aligned}\therefore \text{emf per turn} &= 2 \times (\text{emf per conductor}) \\ &= 2 \times (2f\phi) \\ &= 4f\phi \text{ volt.}\end{aligned}$$



Let T_{ph} be the total no. turns per phase connected in series assuming concentrated wdg. Net emf per phase will be

algebraic sum of the emf per ~~phase~~ turn.

$$\begin{aligned}\therefore \text{Average } E_{ph} &= T_{ph} \times (\text{Average emf per turn}) \\ &= T_{ph} \times 4f\phi.\end{aligned}$$


But in a.c. ckt RMS value is used for analysis.

$$\begin{aligned}\therefore E_{ph}(\text{r.m.s.}) &= 1.11 \times E_{ph}(\text{avg}) \\ &= 1.11 \times 4f\phi \cdot T_{ph}\end{aligned}$$

$$E_{ph}(\text{r.m.s.}) = 4.44 \phi f T_{ph}.$$

$$\left[\text{Where } T_{ph} = \frac{Z_{ph}}{2} \right]$$

Relation betⁿ Mechanical & Electrical Degree



From the above two experiment we come to know that the degree electrical of induced emf is. Number of cycles of the induced emf depends on the number of poles of an alternator.

So for 4 pole alternator, we can write.

$$360^\circ \text{ mechanical} = 720^\circ \text{ electrical}$$

$$\Rightarrow 360^\circ \text{ mechanical} = 360^\circ \times \frac{P}{2} \text{ electrical}$$

$$\text{i.e. } 1^\circ \text{ mechanical} = \left(\frac{P}{2}\right)^\circ \text{ electrical}$$

(where P = Number of Poles)


Armature Winding:-

Armature wdg of alternator is different from d.c. machine because in case of ^{3- ϕ} alternator it carry 3-sets of wdg in such a way that there exists a phase difference of 120° betⁿ them. In d.c. machine wdg is closed but in alternator wdg is open i.e. ~~the~~ six terminals are brought out which finally connected in star or Delta.

* All the coils used for one phase must be connected in such a way that their emf helps each other.

* overall design should be in such a way that the waveform of an Induced emf is almost sinusoidal in nature.

Important Terminology:-



Pole Pitch:-

It is the distance betⁿ the two adjacent Poles.

We have seen that 2-pole are responsible

(6)

For 360° electrical of emf. 4-poles are responsible
for 720° electrical and so on. So one Pole is
responsible for 180° electrical

* So 180° electrical is also called one pole pitch

Key point:- Generally number of ~~pole~~ slots under one
Pole which are responsible for 180° electrical are
measured to specify the pole pitch.

Eg:- If there is 2-poles and 20 slots armature
then under 1-pole there are $\frac{20}{2} = 10$ slots. So
pole pitch is 10 ~~slots~~ or 180° electrical.

$$\therefore \text{Pole Pitch} = 180^\circ \text{ electrical} = \text{slots} / \text{pole} = n.$$

Slot Angle (β):-

The phase difference contributed by
one slot in electrical degree is called slot angle
(β).

We know that


slots / pole contributed 180° electrical.
notation is 'n'.

$$\therefore 1 \text{ slot angle} = \frac{180^\circ}{n}.$$

$$\therefore \beta = \frac{180^\circ}{n}.$$

Eg:- If slots per pole is 10 for 2-pole alternator.

$$\text{then } \beta = \frac{180^\circ}{n} = \frac{180^\circ}{10} = 18^\circ.$$




Types of Armature winding:-

Armature wdg are classified as

- i) Single layer and double layer wdg.
- ii) full pitch and short pitch wdg.
- iii) Concentrated and distributed wdg.

i) Single layer and double layer wdg:-




If a ~~coil~~ slot consists only one coil side, winding is called single layer wdg. But if the slot consists of dual coil side winding, then it is called double layer winding as shown in fig.

* Practically double layer wdg is used becoz in single layer wdg a lot of space get wasted in slots.

(7)

iv) Full Pitch and Short pitch:



If the coil side in one ~~pole~~ slot is connected to a coil side in another slot which is one pole pitch distance away from first slot i.e. 180° electrical, then this type of winding is said to be full pitch winding.

for example:- In 2 pole, 20 slots alternator.

$$\text{Pole pitch } n = \frac{20}{2} = 10 \text{ slots/pole.}$$

So if coil side in slot no-1 is connected to coil side in slot no-11 are one pole pitch @ 180° electrical apart. this coil is full pitch coil.

But if the coils are used in

Such a way that coil span is slightly less than a pole pitch i.e. less than 180° electrical, the coils are called short pitch coil or fractional pitch coil.

* Practically the short pitched coil are used due to some advantages.

* The coil length required is less, so less copper is required. Hence economical.

* It eliminates high frequency harmonics

which distorts the sinusoidal nature of emf. Hence waveform is more sinusoidal.

- * As high frequency is eliminated, so the eddy current and hysteresis loss also minimized, which increase the efficiency.

iii) Concentrated and Distributed wdg:

If all conductors or coils belonging to a phase are placed in one slot under every pole is called Concentrated wdg.

Alternator is 3-phase. i.e. three different set of winding, each for a phase. So depending upon the total number of slots and number of poles, we have certain slots per phase available under each pole. It is denoted as 'm'.

$$m = \text{Slots per pole per phase} = \frac{n}{\text{number of phase}}$$

$$\Rightarrow m = \frac{n}{3} \quad (3\text{-phase})$$

[for example:- In 18 slots, 2 pole alternator.

$$\text{Slots per pole 'n'} = \frac{18}{2} = 9.$$

$$\text{and Slots per pole per phase 'm'} = \frac{9}{3} = 3.$$

So we have 3 slots per pole per phase available.

Now let 'x' number of conductor per phase are to be placed under one pole. If all 'x' conductors per phase are placed in one slot keeping remaining 2 slots empty is concentrated wdg.]

(8)

But if 'x' conductors per phase are distributed amongst the 3 slots per phase available under every pole, the wdg is called distributed wdg.

* Distributed wdg makes the waveform of the induced emf more sinusoidal in nature.

* In concentrated wdg due to large number of conductor per slot, heat dissipation is poor. So practically distributed wdg is used.


Note:- In practical field, generally double layer, shortpitched and distributed type armature wdg is preferred.

- x -

Pitch factor or Coil Span Factor (K_c):-


In practice short pitch coil are preferred. Short pitch coil is less than one pole pitch means less than 180° . The coils is generally shorted by one or two slots.

Note:- The angle by which coils are short pitched is called angle of short pitch denoted as ' α '.



α = Angle by which coils are short pitched.

$$\text{So } \alpha = 180^\circ - \text{Actual Coil Span.}$$




Let 'E' be the induced emf in each coil side. If coil is full pitch coil, the induced emf in each coil side help each other. Hence the resultant emf across a coil will be algebraic sum of the two.



$$E_R = E + E = 2E \rightarrow \text{for full pitch.}$$

Now coil is short-pitched by angle ' α '. So the two coil sides no longer in phase. Hence the resultant emf is also no longer remain algebraic sum of two but become a phasor sum. It is obvious that E_R value is less than E_R in full pitch coil.



Draw AC Perpendicular on OB bisecting OB.

$$\therefore \angle(OA) = \frac{E_R}{2} = \angle(OB)$$

$$\text{and } \angle BOA = \alpha/2.$$

$$\therefore \cos\left(\frac{\alpha}{2}\right) = \frac{OC}{OA} = \frac{E_R}{2E}.$$

$$\Rightarrow E_R = 2E \cos(\alpha/2) \rightarrow \text{for short pitch.}$$

Now "the factor by which induced emf get reduced due to short pitching is known as Pitch factor or coil span factor (k_c).

9

$$K_c = \frac{E_r \text{ when coil is short pitch}}{E_r \text{ when coil is full pitch}}$$

$$\rightarrow r_c = \frac{2E \cos(\theta/2)}{2E}$$


→ $K_c = \cos \frac{\alpha}{2}$ $\alpha \rightarrow$ Angle of short pitch.

Distribution factor:-(K_d)

Similar to full pitch coil, concentrated winding is rarely used.

In Concentrated type all coils are placed in a one slot under one pole. So induced emf in all coil will be in phase, hence resultant emf after connecting coils in series will be algebraic sum of all the emf.

But in case of distributed ~~all~~
wdg all the slots contain the coils, and there
is a slot angle also (β). ~~As~~ Though the magnitude of
emf in each coil is same 'E' and as slot angle
' β ' exist betⁿ the coils, so there is a phase
difference occurs to each other. Hence resultant
emf will be phasor sum of them. So due to distributed
wdg resultant emf decreases.



* "The factor by which there is a reduction in the emf due to distribution of coils is called Distribution factor as (K_d) ."


Derivation of Distribution factor:- (K_d)

Let there are 'n' slots and

'm' slots/pole/Phase so

there is 'm' coils distributed under a pole/phase.
connected in series.

Let 'E' be the induced emf per coil
then all the 'm' emfs induced in the coil will
Phase difference of $\beta = \frac{180^\circ}{n}$.



AB, BC, CD, DE & EF \rightarrow Represents emf per coil.

All the ends are joined at 'O' which is center
of radius 'R'.

$$\text{So } AB = BC = CD = DE = EF = E$$

Let the base angle be ' α '.

$$\angle OAB = \angle OBA = \angle OBC = \angle OCB = \alpha$$

$$\text{and } \angle AOB = \angle BOC = \angle COD = \beta \text{ (say)}$$

Now consider AOB triangle

$$2\alpha + \beta = 180^\circ \text{ ————— (i)}$$


$$\text{while } \angle OBA + \angle OBC + \beta = 180^\circ$$

$$\text{i.e. } 2\alpha + \beta = 180^\circ \text{ ————— (ii)}$$

Comparing eqs ① & ④

$$\gamma = \beta$$

$$\text{So } \angle AOB = \angle BOA = \angle COB = \dots = \beta$$



If 'M' is the last point of the last phaser

$$\text{So } \angle AOM = m \times \beta = m\beta \text{ and}$$

$$AM = E_R = \text{Resultant of all the emf.}$$

Now from the triangle AOB


$$L(AB) = E \quad \text{so } L(AF) = \frac{E}{2}$$

$$\text{and } L(OA) = R.$$

$$\therefore \sin\left(\frac{\beta}{2}\right) = \frac{AF}{OA} = \frac{E/2}{R}.$$

$$\Rightarrow E = 2R \sin\left(\frac{\beta}{2}\right). \quad \text{--- ③}$$

Now consider the triangle OAM from main fig.



$$\angle AOG = \angle GOM = \frac{m\beta}{2}.$$

$$\text{So } L(AM) = E_R, \text{ so}$$

$$L(AG) = \frac{E_R}{2}.$$

$$\therefore \sin\left(\frac{m\beta}{2}\right) = \frac{AG}{OA} = \frac{E_R/2}{R}.$$

$$\Rightarrow \boxed{E_R = 2R \sin\left(\frac{m\beta}{2}\right)} \rightarrow \text{Resultant emf for distributed wdg}$$

Now for concentrated wdg

$$E_R = m \times E$$

$$\text{from eqn (3), } E = 2R \sin\left(\frac{\beta}{2}\right)$$

$$\text{So } \boxed{E_R = 2mR \sin\frac{\beta}{2}} \rightarrow \text{Resultant emf for Concentrated wdg}$$

Now Distribution factor is defined as

$$K_d = \frac{E_R \text{ when coil is distributed}}{E_R \text{ when coil is concentrated}}$$

$$\Rightarrow K_d = \frac{2R \sin\left(\frac{m\beta}{2}\right)}{2mR \sin\left(\frac{\beta}{2}\right)}$$

$$\Rightarrow \boxed{K_d = \frac{\sin\left(\frac{m\beta}{2}\right)}{m \sin\left(\frac{\beta}{2}\right)}}$$

$m = \text{Slots/pole/phase}$

$\beta = \text{Slots angle} = \frac{180^\circ}{n}$

$n = \text{Slots per pole}$

Generalized Eqn of EMF

When we consider full pitch, Concentrated

wdg.

$$E_{ph} = 4.44 \phi f T_{ph}$$

But at the time of short pitch, distribution

wdg

$$\boxed{E_{ph} = 4.44 \phi f K_c K_d T_{ph}}$$

* for full pitch

$$K_c = 1$$

* for concentrated

$$\text{wdg } K_d = 1$$

Parameters of Armature Winding:-


There are three important parameter of armature winding.

- i) Armature Resistance (R_a)
- ii) Armature leakage reactance (X_L)
- iii) Reactance corresponding to Armature reaction.


These three important parameter is help-ful to determine the Regulation of an alternator and drawing the equivalent ckt.

i) Armature Resistance (R_a):-

every armature wdg has its own resistance, the effective resistance is denoted as $R_a \Omega/\text{ph}$.



(for star connection)



(for Delta Connection)

To measure the armature resistance of a alternator we give the d.c. voltage to any two phase.

$$R_{RY} = \text{Resistance betn } R-Y \text{ termin} \\ = R_a + R_a = 2R_a$$


$$\Rightarrow R_a = \frac{R_{RY}}{2} \Omega/\text{ph}$$

$$R_{RY} = R_a \parallel 2R_a \Omega/\text{ph}$$

$$\Rightarrow R_{RY} = \frac{2}{3} R_a$$

$$\Rightarrow R_a = \frac{3}{2} R_{RY} \Omega/\text{ph}$$

Armature Leakage Reactance :-



When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux.

This leakage flux makes the armature wdg inductive in nature. So wdg possesses a wdg reactance in addition to the resistance.

So leakage reactance is given by

$$X_L = 2\pi f L \text{ } \Omega / \text{ph.}$$

* Its value is much higher than armature resistance.

Reactance corresponding to Armature Reaction :-



Due to armature flux and main flux armature reaction comes in to the picture. ~~but armature reaction~~ ^{effect of the} ~~reaction also depends upon~~ the armature flux. Not only depend upon the magnitude of current but also depend upon the nature of power factor of the load connected to load.

Let us see the effect of power factor on the armature reaction.

i) Unity P.f. Load:-

Consider a purely resistive load connected to the alternator, having unity power factor. i.e. E_{ph} and I_{ph} are in phase.

If ϕ_f is the main flux produced by the field wdg responsible for producing E_{ph} , then E_{ph} lags ϕ_f by 90° .



Now current through armature I_a produces armature flux ϕ_a . So ϕ_a and I_a are always in phase in same direction.


It is seen that there exists a phase difference of 90° betⁿ ϕ_a and ϕ_f . From the waveform it is seen that the two fluxes oppose each other on the left half and assist each other at right half of each pole. Hence average flux is constant but its flux distribution gets distorted.

"Such distortion effect of armature reaction under unity P.f. is called Cross magnetizing effect".

Due to this, small voltage drop will occur at the terminals of alternator.

ii) Zero Lagging P.f.:-

Consider a pure Inductive load connected to the alternator having zero lagging P.f. This indicates that I_a is lags by E_{ph} by 90° .





It is seen from phasor diagram that Φ_f and Φ_a are exactly in opposite direction to each other.

"So armature flux tries to cancel the main flux. such an effect of armature reaction is called demagnetising effect."

As this effect causes reduction in the main flux, the terminal voltage drops. T_d drop is higher than unity P.f.

iii) Zero Leading P.f.:-

Consider a Pure Capacitive load having zero leading P.f. connected to alternator. This means that I_{aph} is leads E_{ph} by 90° .



It can be seen from the phasor diagram and waveform that the armature flux and the main flux are in the same direction, i.e. they are helping each other. This results in to the addition in main flux.

"Such an effect of armature reaction due to which armature flux assists field flux is called magnetising effect of armature reaction."

As this effect adds the flux to the main flux, greater emf gets induced in the armature.

Armature Reaction Reactance (X_{ar}):

We have seen that in inductive load demagnetising effect occurs and generally practical loads are inductive in nature. Due to this terminal voltage reduces. This drop is not across any physical element.

But to quantify the voltage drop due to armature reaction, armature reaction is assumed to have a fictitious reactance. This reactance is called Armature reaction Reactance (X_{ar}). and the drop is $I_a X_{ar}$.

Synchronous Reactance and Synchronous Impedance

The sum of the fictitious armature reaction reactance and the leakage reactance of the armature is called synchronous reactance of the alternator denoted as X_s .

So
$$X_s = X_L + X_{ar} \quad \Omega / \text{ph}$$

Now it is possible to define Synchronous Impedance.

"By combining Per phase value of Synchronous reactance and armature resistance is called Synchronous Impedance of alternator, denoted as Z_s ."


$$\text{So } Z_s = R_a + jX_s$$

$$\Rightarrow |Z_s| = \sqrt{R_a^2 + (X_s)^2} \Omega/\text{ph}$$

(Where $X_s = X_L + X_{arr}$)

* Generally Impedance of the ω dg is constant for any machine. But in case of alternator, synch. reactance is depends on load condition and powerfactor. So Z_s also varies with the load.

Equivalent ckt of Alternator:-



Here V_t is less than E_{ph} or E'_{ph} .
from the equivalent ckt.

$$\bar{E}_{ph} = \bar{V}_{tph} + \bar{I}_a \bar{Z}_s \quad (\text{Phasor Sum})$$


$$\Rightarrow \boxed{E_{ph} = V_{ph} + I_a R_a + I_a X_s}$$

This is called voltage equation of an alternator.

from this voltage equation we can draw the phasor diagram for various load power factor and establish the relationship betⁿ E_{ph} and V_{ph} , in terms of armature current, i.e. load current and the power factor ($\cos \phi$).

Phasor Diagram

i) For lagging power factor load:-



$$OD = V_{ph} \cos \phi$$

$$AD = BE = V_{ph} \sin \phi$$

$$DE = I_a R_a$$

Consider ΔOCE , we can write

$$(OC)^2 = (OE)^2 + (EC)^2$$


$$\Rightarrow (E_{ph})^2 = (OD + DE)^2 + (EB + BC)^2$$

$$\Rightarrow (E_{ph})^2 = (V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi + I_a X_s)^2$$

$$\Rightarrow \boxed{E_{ph} = \sqrt{(V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi + I_a X_s)^2}}$$

from this eqⁿ Induced emf can be calculated.

ii) leading powerfactor:-



Considering $\triangle OAD$

$$OD = V_{ph} \cos \phi$$

$$AD = BE = V_{ph} \sin \phi$$

$$DE = I_a R_a$$

Now considering $\triangle OCE$

$$(OC)^2 = (OE)^2 + (EC)^2$$

$$\Rightarrow (E_{ph})^2 = (OD + DE)^2 + (EC)^2$$

$$\Rightarrow (E_{ph})^2 = (OD + DE)^2 + (BE - BC)^2$$

$$\Rightarrow (E_{ph})^2 = (V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi - I_a X_s)^2$$


$$\Rightarrow E_{ph} = \sqrt{(V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi - I_a X_s)^2}$$

*** Note:-** for leading P.f. $I_a X_s$ is negative where as for lagging P.f. $I_a X_s$ is positive, this is because Armature reaction is magnetising in case of leading P.f. & demagnetising in case of lagging P.f.

iii) unity powerfactor:-

unity powerfactor means $\cos \phi = 1$. so

$\phi = 0$ which means V_{ph} is in phase with I_a
So Phasor diagram is drawn as shown below



Considering ΔOBC ,

$$(OC)^2 = (OB)^2 + (BC)^2$$

$$\Rightarrow (E_{ph})^2 = (OA + AB)^2 + (BC)^2$$

$$\Rightarrow (E_{ph})^2 = (V_{ph} + I_a R_a)^2 + (I_a X_s)^2$$

$$\Rightarrow E_{ph} = \sqrt{(V_{ph} + I_a R_a)^2 + (I_a X_s)^2}$$

* As $\cos \phi = 1$ & $\sin \phi = 0$, hence does not appear in the eqn.

* Note:- So it is clear that V_{ph} is less than E_{ph} for lagging and unity p.f. due to demagnetising and cross magnetising effect where as V_{ph} is greater than E_{ph} in case of leading p.f. due to magnetising effect.

Thus in general, for any p.f. condition,

$$(E_{ph})^2 = (V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi \pm I_a X_s)^2$$

+ sign for lagging p.f.
- sign for leading p.f.

from this, we can now define the voltage regulation of an alternator.

Voltage Regulation of an Alternator :-

Under the load condition, the terminal voltage is less than the induced emf E_{ph} . So if the load is disconnected, V_{ph} is ~~same~~ equal to E_{ph} , if flux and speed is maintained constant. This change in the terminal voltage is significant in defining the voltage regulation.


"The voltage regulation of an alternator is defined as the change in its terminal voltage when full load is removed, keeping field excitation and speed constant, divided by the rated terminal voltage.

$$\% \text{ Regulation} = \frac{E_{ph} - V_{ph}}{V_{ph}} \times 100$$

E_{ph} = No load induced emf
 V_{ph} = Rated terminal voltage

The value of the regulation not only depends on the load or load current but also depends on the load power-factor.

For lagging and unity power factor there is always drop in the terminal voltage, hence regulation value is always positive. While the leading power factor, the terminal voltage is increased, hence regulation is negative. The relationship between load current and the terminal voltage is called load characteristics.



(16)

Methods of Determining the Regulation:-

There are various methods to determine the voltage regulation for small alternators; it can be determined by direct loading test while for large capacity alternators it can be determined by synchronous impedance method.

- i) Direct loading method.
- ii) Synchronous Impedance method or EMF method.
- iii) Ampere-turns method or MMF method.
- iv) Zero power factor method or Potier triangle method.
- v) ASA Modification form of MMF method.
- vi) Two reaction theory.

i) Voltage Regulation by Direct Loading:-




fig shows the ckt diagram for conducting the direct loading test. A star connected armature is to be connected to a three phase load by the help of TPST switch. the field winding is excited by separate d.c. supply. To control the flux i.e. the current through field winding, a rheostat is inserted in series with the field wdg.

Procedure:-

- * The alternator is first driven at its synchronous speed N_s .

Now $E_{ph} \propto \phi$

- * By giving d.c. supply to field wdg, the field current is adjusted to adjust the flux, so that the rated voltage is available across the terminals. This can be observed on voltmeter.
- * The load is then connected by means of TPST switch.
- * The load is then increased, so that ammeter reads rated value of current.
- * Again adjust the voltage to its rated value by means of field excitation using a rheostat connected (V_{ph}).
- * Then ~~throw~~ throw off the entire load by the help of ~~top~~ TPST switch, without changing the speed and the field excitation.
- * observe the voltmeter reading. This reading is the no load induced emf (E_{ph}).
- * The rated voltage on full load is V_{ph} .


Now % Regulation = $\frac{E_{ph} - V_{ph}}{V_{ph}} \times 100$.

* Key Point: But for high capacity alternator, that much full load can not be directly connected to the alternator. Hence this method is only for small capacity alternator. (Less than 5 KVA)

ii) Synchronous Impedance Method (Emf Method):

Synchronous Impedance method requires following data to calculate the regulation

- i) The armature resistance per phase (R_a)
- ii) open ckt characteristics which is the graph of open ckt voltage against the field current.
- iii) short ckt characteristics which is the graph of short ckt current against the field current.




(ckt diagram)

Open ckt test:-

The procedure for open ckt test is as follows

- i) Start the prime mover and adjust the speed to synchronous speed.
- ii) Keeping rheostat in the field ckt max. switch on the d.c. supply.
- iii) The TPST switch in the armature ckt is kept open.
- iv) With the help of rheostat, field current is varied from its minimum value to rated value. Due to this flux increases, thus induced emf increases. Voltmeter reading gives the induced emf and Ammeter reading gives the field current.

from this two reading of various value, graph of $(V_{oc})_{ph}$ against I_f is plotted.



Short ckt test:-

After completing open ckt test


- i) The field rheostat is brought to max. position, reducing field current to a minimum value.
- ii) Close the TPST switch. ~~is started~~. As the ammeter

- has negligible resistance, the armature gets short ckted
- iii) Then the field excitation gradually increased till full load current is obtained through armature way. This can be observed on ammeter.
 - iv) Now for different value of I_f and I_{sc} , we can plot the graph of S.C.C.

Determination of Z_s from OCC and SCC.

We know that Z_s will change as load changes.


In short ckt test, external load impedance is zero. The short ckt armature current circulates against the impedance of the armature way which is Z_s . The voltage responsible for driving this short ckt current is induced emf. This can be shown by the equivalent ckt



$$Z_s = \frac{E_{ph}}{I_{sc}}$$

I_{sc} is known, which can be observed on ammeter but internally induced emf can not be observed in short ckt test becoz ~~it~~ it will be zero. So to determine the Z_s it is necessary to determine the value of E_{ph} from O.C.C.

The o.c.c. equivalent ckt will be.



It is clear from the equivalent ckt that as $I_a = 0$, the voltmeter reading $(V_{oc})_{ph}$ will be equal to internally induced emf E_{ph} .

$$\text{So } Z_s = \frac{(V_{oc})_{ph}}{(I_{sc})_{ph}} \text{ for same } I_f.$$

$$\Rightarrow Z_s = \frac{\text{Phase emf on open ckt}}{\text{Phase current on short ckt}} \text{ for same excitation}$$

Regulation Calculation:-

* The armature resistance can be measured by applying d.c. known voltage across the two terminals and measuring current. so value of R_a is also known.

$$\text{Now } Z_s = \sqrt{(R_a)^2 + (X_s)^2}$$

$$\Rightarrow X_s = \sqrt{(Z_s)^2 - (R_a)^2} \text{ per ph. Synchronous Reactance.}$$

No load induced emf per phase

$$E_{ph} = \sqrt{(V_{ph} \cos \phi + I_a R_a)^2 + (V_{ph} \sin \phi \pm I_a X_s)^2}$$

$$\text{So } \% \text{ Regulation} = \frac{E_{ph} - V_{ph}}{V_{ph}} \times 100.$$

Harmonics:-

(19)

In case of alternators, the voltage & current induced are having sinusoidal waveform. But practically we can not get sinusoidal waveform when such alternators are loaded. Such a non sinusoidal waveform is called complex wave.

By Fourier transform, the complex waveform can be shown to be built of a series of sinusoidal wave whose frequency are integral multiple of the frequency of fundamental wave. These sinusoidal component are called harmonics of complex wave.

Consider a complex wave which is represented by

$$e = E_1 \sin(\omega t + \phi_1) + E_2 \sin(2\omega t + \phi_2) + \sqrt{E_3 \sin(3\omega t + \phi_3) + \dots + E_n \sin(n\omega t + \phi_n)}$$

Fundamental Component nth Harmonic Component

The complex wave containing fundamental component and even harmonics only is always unsymmetrical about x-axis. Where as fundamental component & odd harmonics is always symmetrical about x-axis. And in case of alternator, the voltage generated is mostly symmetrical as the field system and coils are all symmetrical.

Effect of Harmonics on pitch & Distribution factor:

a. If the short pitch angle or chording angle is ' α ' degree (electrical) for the fundamental wave, then its value for different harmonics are

for 3rd harmonics = 3α &

for 5th harmonics = 5α .

$\therefore K_c = \cos \alpha/2 \longrightarrow$ for fundamental.

= $\cos 3\alpha/2 \longrightarrow$ for 3rd harmonics

= $\cos 5\alpha/2 \longrightarrow$ for 5th harmonics.

b. for distribution factor.

$K_d = \frac{\sin(m\beta/2)}{m \sin(\beta/2)} \longrightarrow$ for fundamental

= $\frac{\sin(3m\beta/2)}{m \sin(3\beta/2)} \longrightarrow$ for 3rd harmonic

= $\frac{\sin(5m\beta/2)}{m \sin(5\beta/2)} \longrightarrow$ for 5th harmonic

c. frequency also changed. If fundamental frequency is 50 Hz, then.

for 3rd harmonics $\rightarrow f_3 = 3 \times 50 = 150 \text{ Hz}$.

for 5th harmonics $\rightarrow f_5 = 5 \times 50 = 250 \text{ Hz}$, etc.

Parallel operation of two Alternators And Synchronization:

(20)

In utility system, there will be thousands of generator which have to be operated in parallel so that they will get interconnected by thousands of kilometer of transmission line.

When number of generator are operating at same voltage and are require to be interconnected electrically, bus-bar are used as the common electrical component.

"Bus bar are nothing but copper rods which operated at constant voltage".

The process of switching of an alternator to another alternator or with a common bus-bar without any interruption is called synchronization.

or

It is the process of connecting two alternator in parallel without any interruption.

Necessary Condition of Synchronization / Parallel operation:

- i) The terminal voltage of incoming m/c must be same as that of busbar voltage
- ii) The frequency must be same as that of incoming machine with bus-bar.
- iii) The phase of alternator voltage must be identical with phase of bus-bar voltage.

from above three Condition, Cond-1 is indicated by voltmeter, Cond-2 & 3 are indicated by Synchronizing lamp or synchroscope.


Note:- The violence of any of the above condⁿ may cause a circulating current and power surges, Due to this a undesirable electro-mechanical oscillations of rotor will occur.

Parallel operation of two Alternator:-

It can be done by two ways.

- i) Dark lamp method.
- ii) Bright lamp method.


i) Dark lamp method:-




In this method, the lamps are arranged as shown above fig. The alternator to be synchronised, which consists of two lamps connected across the switch terminal of same phase.

(21)

The lamps are connected in such a way that the polarity and frequency of two m/c can be checked. When the frequency is exactly same and voltage is just phase opposition to each other, so no resultant Rmf, under this condⁿ lamp will not glow and at that moment, the switch is closed for parallel operation.




ii) Bright lamp Method:-



Since ~~it~~ it is very difficult to judge the correct instant of zero voltage in lamps dark method. So this method is used for synchronization of two alternator. This is more sharp and accurate method of synchronization because the lamps are much more sensitive to change in voltage at their maximum brightness than when they are dark.

Parallel operation of 3 phase Alternator:



Consider two Alternators A & B to be Synchronised. The alternator A is already running at Synchronous speed and is connected to bus-bar of constant voltage and frequency. The alternator 'B' is connected to bus-bar and its process of synchronization can be explained below:


Step-1: Start the prime mover of the m/c. Adjust its speed to a synchronous speed of m/c-B.

Step-2: By adjusting the excitation to field by the help of rheostat, the induced emf of 'B' is equal to the induced emf of A.

Step-3: By varying remaining condⁿ, the three lamps are used (L_1 , L_2 & L_3) as shown above.

Let the three bus bar voltage are represented by phasors OR , OY & OB rotating at an angular speed of ω rad/sec.



And the incoming m/c voltage are represented by OR' , OY' & OB' , rotating at ω_2 rad/sec.





The Phasor sum ERR' , joining the tips R & R' is voltage across lamp pair L_1 . Similarly EYB' and EBy' are voltage across lamp L_2 & L_3 respectively.

If there is difference betⁿ two frequencies, due to different in speed, the lamp will become dark and bright in a sequence. This sequence tells whether incoming m/c frequency is less or greater than m/c-A.

The Sequence L_1, L_2, L_3 tells that m/c-B is faster, but the sequence L_3, L_2, L_1 tells that m/c-B is slower than m/c-A.






So the Prime mover speed can be adjust accordingly to match the frequency.

So in this method when lamp L1 is dark and other two lamps L2 & L3 are equally bright, at that moment, synchronisation is done. So this method is called "Bright and Dark lamp" method.

Synchronization by Synchroscope:-

The lamp method is not accurate, since it depend on the judgement of the operator. Hence to avoid such, a accurate device is used is known as synchroscope.




It consists of a rotating Pointer which indicate the exact movement of closing the switch. If pointer rotates in anticlockwise direction, it indicate that incoming m/c is running slow, where as clockwise rotation shows the fast. The rotation of pointer is proportional to difference in two frequencies. When the pointer is at vertical position.

The switch is to be closed and the two m/c are connected in parallel.

Distribution of load by parallel connected Alternators:-

Consider two identical alternators connected in parallel as shown below.



The terminal voltage 'V' is given by

$$\bar{V} = \bar{E}_1 - \bar{I}_1 \bar{Z}_1 = \bar{E}_2 - \bar{I}_2 \bar{Z}_2$$

$$\text{or } \bar{V} = \bar{I} \bar{Z}$$

$$\text{Load current } I = I_1 + I_2$$

From the above expression,

$$\begin{aligned} \bar{E}_1 &= \bar{V} + \bar{I}_1 \bar{Z}_1 \\ &= \bar{I} \bar{Z} + \bar{I}_1 \bar{Z}_1 = (\bar{I}_1 + \bar{I}_2) \bar{Z} + \bar{I}_1 \bar{Z}_1 \\ &= \bar{I}_1 (\bar{Z} + \bar{Z}_1) + \bar{I}_2 \bar{Z} \quad \text{--- (1)} \end{aligned}$$

$$\text{Similarly } \bar{E}_2 = \bar{I}_2 (\bar{Z} + \bar{Z}_2) + \bar{I}_1 \bar{Z} \quad \text{--- (2)}$$

Solving eqn (1) & (2), we can get

$$\bar{I}_1 = \frac{(\bar{E}_1 - \bar{E}_2) \bar{Z} + \bar{E}_1 \bar{Z}_2}{\bar{Z}(\bar{Z}_1 + \bar{Z}_2) + \bar{Z}_1 \bar{Z}_2}$$

$$\times \bar{I}_2 = \frac{(\bar{E}_2 - \bar{E}_1) \bar{Z} + \bar{E}_2 \bar{Z}_1}{\bar{Z}(\bar{Z}_1 + \bar{Z}_2) + \bar{Z}_1 \bar{Z}_2}$$

$$\therefore \bar{I} = \bar{I}_1 + \bar{I}_2 = \frac{\bar{E}_1 \bar{Z}_2 + \bar{E}_2 \bar{Z}_1}{\bar{Z} \left[(\bar{Z}_1 + \bar{Z}_2) + \frac{\bar{Z}_1 \bar{Z}_2}{\bar{Z}} \right]}$$

$$\times V = \bar{I} \bar{Z} = \frac{\bar{E}_1 \bar{Z}_2 + \bar{E}_2 \bar{Z}_1}{(\bar{Z}_1 + \bar{Z}_2) + \frac{\bar{Z}_1 \bar{Z}_2}{\bar{Z}}}$$

If no load is connected to the alternator, only circulating current I_{sy} will flow in the circ.
This current is given by

$$I_{sy} = \frac{\bar{E}_1 - \bar{E}_2}{\bar{Z}_1 + \bar{Z}_2}$$

SYNCHRONOUS MOTOR

(01)


Similar to d.c. machine, there is no constructional difference betⁿ Alternator and synchronous motor. If three phase supply is given to the stator of a 3- ϕ Alternator, it can work as a motor. As it is driven at synchronous speed, it is called synchronous motor.

Construction of S.M.:-

Similar to ~~alternator~~ d.c. machine, there is no constructional difference betⁿ Alternator & S.M. It has two main parts.



i) Stator:- It consists of a star or delta connected wdg. This is excited by 3- ϕ A.C. supply.

ii) Rotor:- Rotor is field wdg. Practically most of the S.M. use Salient Pole type. The field wdg is excited by separate d.c. supply.



Principle of operation :-

Synchronous motor works on the principle of magnetic locking. When two unlike poles are brought near to each other, & if magnet are strong, there exist a tremendous force of attraction betⁿ those poles. In such condⁿ, the two magnets are said to be magnetically locked.





In this condⁿ if magnet-1 will rotate, then magnet-2 also rotated in the same direction along with this due to magnetic locking.

In S.M. motor, we give the 3- ϕ supply to stator wdg & produces a rotating magnetic field which is rotated at synchronous speed. So it creates N_1 & S_1 pole in stator. Let there is two poles N_1 & S_1 . Now we give the d.c supply to the rotor, and it will also create two poles let N_2 & S_2 .

Now one magnet is rotating at N_1 & S_1 while at start, rotor is stationary i.e. second magnet is N_2 & S_2 . If somehow, the unlike pole N_1 & S_2 or S_1 & N_2 are brought near to each other, the magnetic locking is get establish betⁿ stator & rotor poles. As the stator poles are rotating, the rotor poles are also rotate in same direction.

Why synchronous motor is not self starting:-



Consider an instant when two poles are at such a position where stator magnetic axis is vertical as shown above.

At this instant, rotor poles are arbitrarily positioned as shown.

At this instant, rotor is stationary and unlike poles are try to attract each other. Due to this, rotor is subjected to an instantaneous torque in anticlockwise direction as shown in fig-1.

But stator poles are rotating very fast i.e. at a speed of N_s r.p.m. Due to inertia before rotor rotates, the stator pole changes their position. Consider an instant, half a period, where stator poles are reversed but due to inertia, rotor poles are unable to rotate. This is shown in fig-2.

At this instant, due to unlike pole try to attract each other, the rotor will try to rotate in clockwise direction. But before this stator poles again changes and rotor will not able to rotate. Hence it is not self starting.

Procedure to start a synchronous motor:-

The general procedure to start a S.M. are

- i) Give a 3- ϕ A.C. supply to stator wdg. It will produce rotating magnetic field at N_s r.p.m.
- ii) then drive the rotor by some external means like diesel engine in the direction of r.m.f. at a speed of near to or equal to synchronous speed (N_s).
- iii) switch ON the d.c. supply given to the rotor which will produce rotor poles.
- iv) At a particular instant, both the field sets magnetically locked. The stator field pulls rotor field in to synchronizing. Then the external device is removed, but the rotor will continue to rotate at a speed of N_s due to magnetic locking.

Method of starting the synchronous motor:-

The various method to start the

S.M. are

- i) using pony motor.
- ii) using Damper wdg.
- iii) As a slip ring I.M.
- iv) using small d.c. machine couple to it.

i) Using pony motor:-


In this method, the rotor is brought in to synchronous speed with the help of some external device like small induction motor.

(03)

such an external device is called Pony motor.

once the rotor attains the synchronous speed, the d.c. excitation to the rotor is switched-on. once the synchronizing is established, Pony motor is decoupled.

ii) using Damper winding:-




So S.M. in addition to the normal field wdg, a additional winding consisting of copper bars placed in the slots in the pole faces. the bars are short circuited with the help of end rings. Such a additional wdg is called damper wdg.

So once the stator is excited by 3- ϕ supply, the S.M. starts to rotate like a Induction motor due to the damper wdg. Then a D.C. supply is given to field wdg. At a particular instant motor gets pulled in to synchronizing and starts rotating at a synchronous speed. As rotor rotates in synchronous speed, the relative motion between damper wdg & rotating magnetic field is zero. Hence when motor is running as synchronous motor, there can not be any induced emf in damper winding. So damper wdg only active on starting condⁿ.

iii) As a slip ring I.M.:

The above method does not provide high starting torque. So to achieve this, instead of shorting the damper wdg, it is designed to form a 3- ϕ star ~~Delta~~ connected wdg. The three ends are brought out through slip ring. An external rheostat is connected in series with rotor circ. So when stator is excited, the motor starts as a slip ring induction motor and due to the resistance added in the rotor provided the high starting torque. The resistance is then gradually cut-off, when rotor gathers speed. When motor pulled in to synchronizing, d.c. excitation is provided to rotor and it will run as synchronous motor.



iv) Using small d.c. machine:

many times, a large S.M. are provided with coupled with d.c. machine. This machine is used as a d.c. motor to rotate the S.M. at a synchronous speed. then the excitation is given to rotor wdg. Once the motor runs as a S.M. the same d.c. motor acts as a d.c. generator called ~~exciter~~.

Concept of Load Angle (δ):

When a d.c. motor or Induction motor is loaded the speed decreases. But in case of synchronous motor, speed always constant.

In d.c. motor, armature develops an emf after motoring action, which opposes the supply voltage, is called back emf. E_b .

$$\text{So } I_a = \frac{V - E_b}{R_a} \quad \text{where } E_b = \frac{\phi Z N P}{60 A}$$

In S.M. also, once rotor starts at synchronous speed, an emf is induced in stator which opposes the supply voltage. This emf is also called back emf E_{bph} in synchronous motor. Here

$$E_{bph} = 4.44 K_c K_d \phi f T_{ph}$$

$$E_{bph} \propto \phi$$

As speed is constant, the frequency also constant. So magnitude of back emf controlled by changing the flux ϕ produced by rotor.

Like d.c. motor Here also


$$I_{aph} = \frac{V_{ph} - E_{bph}}{Z_s}$$

(Here vector addition)

gn Ideal condition, i.e. at no losses condⁿ

$$V_{ph} = E_{ph}$$

→ matching of two axes.



Under this condition, the magnetic locking betⁿ stator and rotor is such a way that the magnetic axis of both coincide with each other. This is said to be ideal condⁿ.
The phasor diagram for this

condⁿ is




$$|E_{ph}| = |V_{ph}|$$

$$\text{Now } \bar{I}_a = \frac{V_{ph} - \bar{E}_{ph}}{X_s}$$


But in vector difference $V_{ph} - \bar{E}_{ph} = 0$.
Hence $I_a = 0$, which is not possible.

So in practical condⁿ




(05)

Due to various losses, the magnetic locking exist betⁿ stator & rotor but in such a way that there exists a small angle difference betⁿ the axes. This angle is called load angle, power angle, coupling angle, torque angle or angle of retardation & denoted as ' δ '.



$$\bar{V}_{ph} - \bar{E}_{ph} = \bar{I}_a \bar{Z}_s$$

$$\therefore OB = \bar{I}_a \bar{Z}_s = \bar{E}_{Rph}$$




Effect of varying load with constant excitation:-

As E_{ph} depends on flux, for constant excitation E_{ph} also constant. For constant excitation, if load is varied then δ keeps on changing. Due to which $\bar{V}_{ph} - \bar{E}_{ph} = \bar{E}_{Rph} = \bar{I}_{aph} \bar{Z}_s$ also changes. As δ increases $I_{aph} \bar{Z}_s$ increases and motor draws more current.

So from above discussion, it is clear that on no load, current drawn by the motor is very small as δ is small.

As load increases, rotor magnetic axis starts retarding i.e. load angle ' δ ' increases. As δ increases this weakens the force maintaining the magnetic locking, though torque produce by the motor increases. As δ reaches up to 90° electrical, flux lines get broken & motor stops.



Effect of varying ~~load~~ Excitation with constant load.

We have seen that with constant excitation with load changes, current drawn by the motor increases.

But if excitation i.e. field current is changed keeping load constant, S.M. reacts by changing its powerfactor of operation.

At start, Consider normal excitation motor drawing certain current I_a & the power factor is lagging. Now when excitation is change, so E_b also changes but the power input is constant as load constant.

$$\text{Now } P_{in} = \sqrt{3} V_L I_L \cos \phi = 3 V_{ph} I_{ph} \cos \phi.$$

Most of the time voltage applied to the motor is constant. Hence for constant power input as V_{ph} is constant, $I_{ph} \cos \phi$ remain constant.

i) UNDER EXCITATION:-

The motor is said to be under excited, if field excitation is such a way that $E_b < V$. Under such condition, the current I_a lags behind V , so that power factor is lagging. as shown in fig (1). Since $E_b < V$, the net voltage E_r decreases. ~~As~~ ^{turn clockwise.} angle ' θ ' betⁿ E_b & I_a is constant, therefore phasor I_a also turns clockwise. Consequently, the motor has a lagging P.f.

ii) NORMAL EXCITATION:-

The motor is said to be normally excited, if the field excitation is such a way that $E_b = V$. as shown in fig-2. Note that the effect of increasing excitation is turn the phasor E_b and hence I_a in the anti-clockwise direction. i.e. phasor I_a comes closer to phasor ' V '. therefore P.f. increasing through still lagging. Since input power is unchanged the stator current I_a must decrease with increase in P.f.


Suppose the field excitation is increased until the current I_a is in phase with the applied voltage ' V ', making the P.f. of the S.M. unity. as shown in fig-3. for a given load at

unity p.f., the resultant E_r & I_a is minimum.


iii) OVER EXCITATION :-

The motor is said to be over excited, if field excitation is such a way that $E_b > V$. Under such condition I_a leads V and the motor power factor is leading as shown in fig-4. Note that E_r and hence I_a further turn anticlockwise from normal excitation position.


From the above discussion, it is conclude that if ~~the~~ the excitation is increases with constant load, the p.f. also increases. Note that armature current I_a is minimum at unity p.f. and increases as the p.f. becomes poor, either leading or lagging.




(fig-1) under excitation.
($E_b < V$)



(fig-2) Normal excitation.
($E_b = V$)



(fig-3) unity p.f.
($E_b > V$)



(fig-4) over excitation
($E_b > V$)

(07)

Torque & Power Develop in S.M.

Net input to S.M. is the 3- ϕ input to stator

$$\therefore P_{in} = 3 V_L I_L \cos \phi$$

$$\Rightarrow P_{in} = 3 (\text{per phase power}) = 3 \times V_{ph} \times I_{ph} \times \cos \phi$$

Now in stator, due to its resistance R_a /phase there are stator Cu. loss

$$\therefore \text{Total stator Cu. loss} = 3 \times (I_{aph})^2 \times R_a$$

The remaining power is converted to the mechanical power, called gross mechanical power developed by the motor denoted as P_m .

$$\therefore P_m = P_{in} - \text{stator Cu. loss.}$$

In d.c. motor, gross mechanical power developed is $E_b \times I_a$. Similarly in S.M. the electrical equivalent of gross mechanical power developed is given by

$$P_m = 3 \times E_{bph} \times I_{aph} \times \cos(\angle E_{bph} \angle I_{aph})$$

$$\text{For lagging p.f.} \rightarrow \angle E_{bph} \angle I_{aph} = \phi - \delta$$

$$\text{For leading p.f.} \rightarrow \angle E_{bph} \angle I_{aph} = \phi + \delta$$

$$\text{For unity p.f.} \rightarrow \angle E_{bph} \angle I_{aph} = \delta$$

So in general.

$$P_m = 3 E_b I_a \cos(\phi \pm \delta)$$

+ \rightarrow for leading
- \rightarrow for lagging

Now in Mechanical point of view.

$$P = T \times \omega$$

$$\Rightarrow P_m = T_g \times \frac{2\pi N_s}{60}$$

$$\Rightarrow T_g = \frac{P_m \times 60}{2\pi N_s} \text{ N-m.}$$

$$\Rightarrow T_g = 9.55 \frac{P_m}{N_s} \text{ N-m.}$$

Mechanical power developed by a Motor :-
(Neglecting R_a)




fig. shows the phasor diagram for under-excited S.M. driving a mechanical load. Since Armature resistance is assumed to be zero, $\tan \theta = \frac{X_s}{R_a} = \infty$ and hence $\theta = 90^\circ$.

$$\therefore \text{input power/phase} = V I_a \cos \phi.$$

(08)

Since R_a is zero, so stator Cu. loss ($I_a^2 R_a$) will be zero. Hence input power is equal to the mechanical power ' P_m ' developed by the motor.

$$\therefore P_m = V I_a \cos \phi \text{ ————— (i)}$$

Now from phasor diagram.

$$AB = E_b \cos \phi = I_a X_s \cos \phi$$

$$\text{Also } AB = E_b \sin \delta$$

$$\therefore I_a X_s \cos \phi = E_b \sin \delta$$

$$\Rightarrow I_a \cos \phi = \frac{E_b \sin \delta}{X_s}$$

Now substituting the value of $I_a \cos \phi$ in eqn (i)

$$\therefore \boxed{P_m = \frac{V E_b}{X_s} \sin \delta} \text{ ————— Per phase.}$$

$$= \frac{3 V E_b}{X_s} \sin \delta \text{ ————— for 3-phase.}$$

It is clear from the above relation that mechanical power with torque angle, and its max. value reached when $\delta = 90^\circ$.


$$\therefore \boxed{P_{\max} = \frac{V E_b}{X_s}}$$

Power Angle Characteristics:-

We know that

$$P_m = P_i = \frac{E_b \cdot V}{X_s} \sin \delta$$


The relationship betⁿ ' P_i ' and ' δ ' is known as Power angle characteristics, of the machine.



The max. power occurs at $\delta = 90^\circ$. Beyond this point, the machine falls out of step and loses synchronism. The machine is normally operated at δ much less than 90° .


Effect of Excitation on Armature current & Power factor:-

We know that if excitation is varied from very low (under excitation) to very high (over excitation) values, then I_a decreases up to unity power factor and then again increases. But initially current is lagging and then it is leading. This can be plotted as shown betⁿ T_a & I_f .



The shape of this plot looks like an english alphabet 'V'. Such curve is called V-curve.

As against this, if the power factor ($\cos \phi$) plotted against field current (I_f), then the shape of the graph looks like an inverted 'V'. Such curve obtained by plotting p.f. against I_f . This graph is called inverted 'V' curve.



Hunting in Synchronous Motor:-

It is seen that, when S.M. is on no load, the stator & rotor poles axis almost coincide with each other.

But when motor is loaded, the rotor pole axis falls back with respect to stator. If the load is suddenly changed by a large amount, the rotor tries to retard to take new

equilibrium position. But due to inertia of the rotor, it can not achieve its final position instantaneously. This will produce more torque than what it is demanded. This will try to reduce the load angle. & rotor swings in other direction.

Such oscillation of the rotor about its new equilibrium position, due to sudden application or removal of load is called Hunting of synchronous motor.

Due to hunting, ' δ ' changes with constant excitation, hence current drawn by the motor changes, ~~so~~ which may cause problem to the other appliances connected to the same line. The changes in armature current not desirable.

Function of Damper winding:-

The damper wdg is provided in the pole faces. When rotor starts oscillates, a relative motion betⁿ damper winding and rotating magnetic field is created. Due to this emf gets induced in the damper winding. According to Lenz's law the direction of induced emf is always so as to oppose the cause inducing it. The cause is hunting. So such induced emf oppose the hunting. Thus hunting is minimized due to damper winding.

1 Application of Synchronous motor.

Due to constant Speed characteristics, S.M. is used in machine tools, motor generator sets, synchronous clock, stroboscopic device, timing device, compressors, fan & blowers, centrifugal pump, vacuum pump, pulp grinder, textile mills, paper mills, rolling mills, cement mills etc.

By adjusting the excitation, the S.M. can also be used for power factor improvement in transmission line.

The disadvantages of S.M. are high cost, necessity of frequent maintenance, and need a d.c. excitation source and a auxiliary device or extra winding to make it self starting.


∴ Induction Motor ∴

①

On whole over world 80% A.C. motor are 3-phase Induction motor. It is because of its some special advantages. The advantages are


- i) Self starting property.
- ii) No need for starting device.
- iii) higher power factor.
- iv) Good speed regulation.


The working principle of 3-phase Induction motor is based on the production of rotating magnetic field.



So a 3-phase I.M. is also called rotating transformer because it operates on the principle of mutual induction like x^r .

Production of rotating magnetic field






$$\Phi_A = \Phi_m \sin \omega t$$

$$\Phi_B = \Phi_m \sin(\omega t - 120^\circ)$$

$$\Phi_C = \Phi_m \sin(\omega t - 240^\circ)$$

In this above figure, we give the 3-phase supply to the stator of an I.M. Here each phase contains 2-pole & each phase is placed 120° apart to each other. Now we give the 3-phase supply (I_A, I_B, I_C) which is sinusoidal in nature.




In this 3-phase waveform we will consider three critical positions (Position-1, 2, & 3) and we will see what happens to magnetic field flux when time increases in the stator field.

Position-1

At Position-1, Current I_A is max. & +ve direction.
 Current I_B is phase-ve & half.
 Current I_C is phase-ve & half.

②




$$\theta = 90^\circ$$

$$\phi_A = \phi_m \sin 90^\circ = \phi_m$$

$$\phi_Y = \phi_m \sin(90^\circ - 120^\circ) = -\frac{\phi_m}{2}$$

$$\phi_Z = \phi_m \sin(90^\circ - 240^\circ) = -\frac{\phi_m}{2}$$



Position-2:-

on Position-2



$$\therefore \phi_R = \phi_m + \frac{\phi_m}{2} \cos 60^\circ + \frac{\phi_m}{2} \cos 60^\circ$$

$$\boxed{\phi_R = 1.5 \phi_m}$$

Current I_B is max. & +ve direction.

Current I_A is half & -ve Phase

Current I_C is half & -ve Phase.





Position-3:-

on this position

Current I_C is max. & +ve direction

Current I_A is -ve phase & half.

Current I_B is -ve phase & half.



So from the above three experiment, we conclude that as time progress, the flux place is changing i.e. it creates its own rotating magnetic field.

In this way a rotating magnetic field is created which is rotated in a synchronous speed denoted as N_s .

Principle of operation:-

The IM rotates as same principle of d.c. motor called Lorentz's force. When the rotating magnetic field (N_s) cuts the rotor conductor and as the rotor conductor are short circuited at both ends a current is induced in that conductor which has its own magnetic field. Due to this a force is created which generates a torque & this torque helps to rotate the rotor in the same direction of N_s . i.e. rotor speed N_r follows the N_s . So there is a relative speed difference between them.

When rotor is at standstill, the speed difference is high but when rotor starts to rotate, the relative speed difference decreases, due to this emf is also decreased. Hence due to decrease in emf the rotor current decreases. Thereby reducing torque of the rotor. So as the torque of the rotor decreases, the rotor speed slows down & it does not catch up the speed of field flux. This difference is called slip.

Slip (S):-

We have seen that rotor rotates in the same direction as that of rotational magnetic flux in stator. But in steady state attains a speed less than the synchronous speed.

③

The difference betⁿ the two speed i.e. synchronous speed (R.M.F) N_s and rotor speed N_r is called slip speed.

So slip of Induction motor can be defined as "the difference betⁿ synchronous speed (N_s) and actual speed of rotor (N_r)".

Thus
$$S = \frac{N_s - N_r}{N_s} \quad \text{--- ①}$$

% slip is expressed as

$$\% S = \frac{N_s - N_r}{N_s} \times 100 \quad \text{--- ②}$$

from eqn ①

$$S = \frac{N_s - N_r}{N_s}$$

$$\Rightarrow S N_s = N_s - N_r$$

$$\Rightarrow \boxed{N_r = N_s(1-S)}$$

Actual Speed of rotor in term of slip.

At stand-still condition, $N_r = 0$

So $0 = N_s(1-S)$


$$\Rightarrow S = \frac{N_s}{N_s} = 1$$

$$\Rightarrow \boxed{S = 1}$$

When $N_r = N_s$, (not possible in case of I.M.)



$$\boxed{S = 0}$$

Speed of Rotational Magnetic field:-




Consider any one phase wound with 2-pole. Let its a imaginary dumbbell in the rotor. we give the sinusoidal wave form to coil-A.

At Position 'A', Here the flux density is zero, b'coz $I_A = 0$, so $MMF(NI) = 0$. The imaginary dumbbell represents the magnitude of flux.
So at Position-A, the imaginary dumbbell looks like as below fig.



As the magnitude of I_A increases, the dumbbell size or magnitude of flux also increases. At point 'C' it increases to its max. value. These are the dumbbell position in case of +ve half cycle.

Now on -ve half cycle, also same but the dumbbell changes its Polarity.



(4)

So from above experiment, we conclude that the imaginary dumbled rotates 180° per half cycle. So for full cycle, it rotates 360° .

So in 'T' sec dumbled rotates 1-revolution.
 1 sec. dumbled rotates $\frac{1}{T}$ revolution.
 so 60 sec. dumbled rotates $\frac{60}{T}$ revolution

So speed of dumbled.

$$N_s = \frac{60}{T} = 60f \text{ r.p.m. per no. of Pole Pair}$$

$$\text{So } N_s = \frac{60f}{\text{no. of Pole Pair.}}$$

$$\Rightarrow N_s = \frac{60f}{P/2} = \frac{120f}{P}$$

$$\Rightarrow \boxed{N_s = \frac{120f}{P}}$$

This speed of rotating magnetic field is called Synchronous speed.


Construction of I.M.:-

Basically, the I.M. consists of two main parts.

- i) The part consisting 3-phase wdg which is stationary called stator.
- ii) The part which rotates & connected to the mechanical load through shaft called rotor.

i) stator:-

It consists of a steel frame which encloses a hollow, cylindrical core made up of thin lamination of silicon steel to reduce hysteresis and eddy current losses. A number of evenly spaced slots are provided on the inner periphery of the lamination.



The insulated conductors are placed in the stator slots and are suitably connected to form a ~~circuit~~ 3-phase star or delta connected ckt. The 3-phase stator wdg is wound for a definite number of poles as per requirement of speed.


* Greater number of poles, means lesser speed.
* vice-versa.

ii) Rotor:-

The rotor is placed inside the stator. The rotor core is also laminated in construction and uses cast iron. It is cylindrical with slots on its periphery. There are two types of rotor construction which are used for induction motor are,

i) Squirrel cage rotor ii) slip-ring or wound rotor.

i) Squirrel-cage rotor:-




The rotor core is cylindrical & slotted. The rotor consists of uninsulated copper or aluminium bars called rotor conductors. The bars are placed in the slots. The bars are permanently shorted at each

⑤

end with the help of conducting copper ring called end ring. The entire structure looks like a cage, forming a closed electrical ckt. so this rotor is called squirrel cage rotor.

As the bars are permanently shorted to each other through end ring, the entire rotor is also called short ckted rotor.

ii) Slip ring Rotor or wound rotor:-



In this type of construction, rotor winding is exactly similar to the stator. The rotor carries a three phase star or delta connected, distributed wdg. wound for same number of poles as that of stator. The three ends of three phase wdg available after connecting the wdg in star or delta are permanently connected to the slip rings. The slip rings are mounted on the same shaft. We have seen that slip rings are used to connect external stationary ckt to the internal rotating ckt.

In this way, the value of rotor resistance per phase can be controlled. This helps us to control some of the important characteristics of the motor like starting torque, speed etc.

Comparison of Squirrel cage & wound rotor

<u>Slip ring rotor</u>	<u>Squirrel-cage rotor</u>
* Rotor consists of 3-phase Δ way.	* Rotor consists of Copper bar
* Resistance can be added externally	* Resistance can not be added
* Slip ring & brushes are Present	* Slip ring & brushes are absent.
* Rotor are Costly.	* Rotor are Cheap
* only 5% of Induction motor in industry uses slip ring rotor.	* very common, about 95% uses.
* High starting torque can be obtained	* Moderate starting torque which can not be controlled.
* Rotor cu. loss is high so efficiency is low.	* Rotor cu. loss is less, so efficiency is high.
* used for lifts, hoists, cranes, elevators, compressor etc	* used for lathes, drilling machine, fans, blowers, water pumps, grinder, pointing m/c etc.

Speed of Rotational Magnetic field (N_s)

we know that

1° mechanical = 1° electrical for 2 poles

But 1° mechanical = $\left(\frac{P}{2}\right)$ electrical for more than 2 poles

Let Speed of Rotation of R.M.F. be N rpm. so in one second it will complete $(N/60)$ revolution. That is

$\frac{N}{60} \times \frac{1}{2}$ Cycle per second.

$\therefore f = \text{frequency} = \text{cycle/sec} = \frac{N}{120}$

$$\Rightarrow N_s = \frac{120f}{P}$$

(6)

Effect of Slip on Rotor Parameter:-

In case of X_r the frequency is same for primary as well as secondary also. But Induction motor secondary part (rotor) is a rotating part. When rotor is at standstill i.e. $N_r = 0$, slip = 1 and hence stator frequency is same as rotor frequency. But when rotor gathers speed, induction motor has some slip corresponding to speed N . Due to this some parameter also get affected. These parameters are

- i) Rotor frequency. ii) Magnitude of rotor induced emf
- iii) Rotor reactance iv) Rotor power factor v) Rotor current

i) Effect on Rotor Frequency:-

At starting $N_r = 0$, $s = 1$. So

~~But~~ frequency of stator = frequency of rotor.

But when rotor rotates some speed, the relative speed difference decreases and hence emf also. If f_r is the rotor frequency in running condition at slip speed $(N_s - N_r)$, then there exist a fixed relation betⁿ $N_s - N_r$, f_r and P .

$$N_s - N_r = \frac{120 f_r}{P} \quad \text{(Rotor Pole = Stator Pole)} \quad \text{--- (1)}$$

We know that the speed of rotating magnetic field is

$$N_s = \frac{120 f}{P} \quad \text{--- (2)}$$

Now dividing eqn ① to ②.

$$\frac{N_s - N_r}{N_s} = \frac{(120f_r/p)}{(120f/p)}$$

But we know that

$$s = \frac{N_s - N_r}{N_s}$$

$$\Rightarrow s = \frac{f_r}{f}$$

$$\Rightarrow \boxed{f_r = sf}$$

Thus frequency of rotor induced emf in running condition is slip times the supply frequency.

ii) Effect on magnitude of rotor Induced emf:

We have seen that

When $N_r = 0$, $s = 1$, At this condition relative speed is maximum & hence max. emf gets induced in the rotor. Let this emf be

E_2 = Rotor induced emf at standstill condition.

As rotor gains speed, the relative speed decreases and hence emf also decreases. Let

E_{2r} = Rotor induced emf at running cond.

Now $E_2 \propto N_s$ while $E_{2r} \propto N_s - N_r$

Dividing the two proportionality equation.

(7)

$$\frac{E_{2s}}{E_2} = \frac{N_s - N_r}{N_s}$$

$$\Rightarrow \frac{E_{2s}}{E_2} = s.$$

$$\Rightarrow \boxed{E_{2s} = s E_2}$$

Thus magnitude of induced emf in the rotor also reduces by slip times the magnitude of induced emf at standstill

iii) Effect on Rotor Resistance and Reactance:-

The rotor winding has its own resistance and Inductance. In general, let

R_2 = Rotor resistance / phase at standstill

X_2 = Rotor reactance / phase at standstill

We know that Resistance is independent of frequency
But reactance is depend on frequency i.e. rotor frequency.

on running condition $f_r = s f$.

$\therefore X_{2s}$ = reactance / phase at running condition

$$X_{2s} = 2\pi f_r L_2 \quad (L_2 = \text{inductance of rotor})$$

$$\Rightarrow X_{2s} = 2\pi (s f) L_2$$

$$\Rightarrow X_{2s} = s \cdot (2\pi f L_2)$$


$$\Rightarrow \boxed{X_{2s} = s \cdot X_2}$$

Hence impedance will be.

$$\begin{cases} Z_2 = \sqrt{R_2^2 + X_2^2} \text{ } \Omega / \text{Phase} \rightarrow \text{At standstill.} \\ Z_{2s} = \sqrt{R_2^2 + (s X_2)^2} \text{ } \Omega / \text{Phase} \rightarrow \text{At running.} \end{cases}$$

iv) Effect on Rotor power factor:-


At standstill, the impedance triangle of rotor will be.



$\cos \phi_2 = \text{Rotor Powerfactor on standstill.}$

$$\Rightarrow \cos \phi_2 = \frac{R_2}{Z_2} = \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

But at running condition, the impedance triangle will be.



$$X_{2s} = S \cdot X_2$$
$$Z_{2s} = \sqrt{R_2^2 + (S X_2)^2}$$

$\cos \phi_{2s} = \text{Rotor Powerfactor on running.}$

$$\Rightarrow \cos \phi_{2s} = \frac{R_2}{Z_{2s}} = \frac{R_2}{\sqrt{R_2^2 + (S X_2)^2}}$$

Note:- As rotor winding is inductive, the rotor p.f. is always inductive in nature.


v) Effect on Rotor Current:-

Let I_2 = rotor current at standstill.

The rotor current depend upon E_2 (emf) and impedance (Z_2) per phase.

$$\therefore I_2 = \frac{E_2}{Z_2}$$

$$\Rightarrow I_2 = \frac{E_2}{\sqrt{R_2^2 + X_2^2}} \text{ A.}$$




Let I_{2s} = rotor current at running condition.

At running condition

$$I_{2s} = \frac{E_{2s}}{Z_{2s}}$$

$$\Rightarrow I_{2s} = \frac{sE_2}{\sqrt{R_2^2 + (sX_2)^2}}$$



Note:- * ϕ_{2s} is angle betⁿ E_{2s} and I_{2s} which decides P.f. at running condition.

* ϕ_2 is angle betⁿ E_2 & I_2 which decides P.f. at standstill condition.

Torque Equation:-

The torque produced in the I.M. depends on following factors

- i) The part of rotating magnetic field (ϕ) which reacts with rotor and is responsible to produce induced emf on rotor (E_2)
- ii) Magnitude of rotor current (I_{2r})
- iii) The power factor of rotor ckt in running cond. ($\cos \phi_{2r}$)

$$\text{So } \boxed{T \propto \phi I_{2r} \cos \phi_{2r}} \text{ ————— (1)}$$

The flux produced by stator is proportional to E_1
i.e. $\phi \propto E_1$ ————— (2)

While E_1 & E_2 are related to each other through turns ratio (like x^r)

$$\text{i.e. } \frac{E_2}{E_1} = k \text{ ————— (3)}$$

So by using eqn (2) & (3), we can write

$$E_2 \propto \phi$$

So in eqn (1), ϕ can be replaced by E_2 .

$$\therefore T \propto E_2 I_{2r} \cos \phi_{2r} \text{ ————— (4)}$$

(9)

while

$$I_{20} = \frac{E_{20}}{Z_{20}} = \frac{SE_2}{\sqrt{R_2^2 + (SX_2)^2}}$$

$$\text{and } \cos\phi_{20} = \frac{R_2}{Z_{20}} = \frac{R_2}{\sqrt{R_2^2 + (SX_2)^2}}$$

So Equation (4) will be

$$T \propto E_2 \cdot \frac{SE_2}{\sqrt{R_2^2 + (SX_2)^2}} \cdot \frac{R_2}{\sqrt{R_2^2 + (SX_2)^2}}$$

$$\Rightarrow T \propto \frac{SE_2^2 R_2}{R_2^2 + (SX_2)^2} \quad \text{N-M}$$

$$\Rightarrow T = \frac{KSE_2^2 R_2}{R_2^2 + (SX_2)^2}$$

(K = Proportionality constant)

$$\therefore K = \frac{3}{2\pi n_s} \quad (\text{for 3-Phase I.M})$$

$$\therefore T = \frac{3}{2\pi n_s} \cdot \frac{SE_2^2 R_2}{R_2^2 + (SX_2)^2}$$

 $n_s \rightarrow$ Synchronous Speed in r.p.s.

$$\Rightarrow \left(n_s = \frac{N_s}{60} \right)$$

Starting torque : (T_{st})

At Starting of I.M.

$N_s = 0$, Slip = 1, So putting these value in above eqn.

$$T_{st} = \frac{3}{2\pi n_s} \cdot \frac{E_2^2 R_2}{R_2^2 + X_2^2}$$

from the above, we can conclude that by changing the value of R_2 , we can control the ^{starting} torque of an Induction motor which is applicable in case of slip ring Induction motor. Where external resistance can be added.

Condition of Max. Starting torque:

Generally stator supply voltage E_1 is constant, that means E_2 is also constant.

$$\text{So } T_{st} = \frac{3}{2\pi n_s} \cdot \frac{E_2^2 R_2}{R_2^2 + X_2^2}$$

$$\Rightarrow T_{st} = \frac{K R_2}{R_2^2 + X_2^2} \quad \left(\text{E}_2 \text{ is constant} \right)$$

Starting torque will be max. when $\frac{dT_{st}}{dR_2} = 0$.

$$\therefore \frac{d}{dR_2} \left(\frac{K R_2}{R_2^2 + X_2^2} \right) = 0$$

$$\Rightarrow K \left[\frac{1}{(R_2^2 + X_2^2)} - \frac{R_2 (2R_2)}{(R_2^2 + X_2^2)^2} \right] = 0$$

$$\Rightarrow \frac{1}{R_2^2 + X_2^2} = \frac{R_2 (2R_2)}{(R_2^2 + X_2^2)^2}$$


$$\Rightarrow R_2^2 + X_2^2 = 2R_2^2$$

$$\Rightarrow \boxed{R_2 = X_2}$$

(10)

So starting torque will be max. when

$$\boxed{\text{Rotor resistance / phase} = \text{standstill rotor reactance / phase}}$$



$$\text{As } R_2 = X_2$$

$$\text{So } \phi_2 = 45^\circ$$

i.e. $\cos \phi_2 = 45^\circ$ i.e. 0.707 lagging in this cond.

Effect of change in supply voltage on starting torque

Generally the supply voltage V or E_1 is constant. But if it varies, then starting torque will change.

We know that

$$T_{st} = \frac{K E_2^2 R_2}{R_2^2 + X_2^2}$$

$$\text{Since } E_2 \propto E_1 \propto V$$

$$\text{So } T_{st} = \frac{K V^2 R_2}{R_2^2 + X_2^2}$$

$$\Rightarrow \boxed{T_{st} \propto V^2}$$

Note:- So starting torque is very sensitive to supply voltage. If drop of 10% supply voltage will

decrease the starting torque by about 20%.

Condition for max. Torque:- (T_m) (Running condⁿ)

We know that

$$T = \frac{K s E_2^2 R_2}{R_2^2 + (s X_2)^2} = \frac{3}{2\pi n_s} \cdot \frac{3 E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

As E_1 is constant E_2 also constant. Similarly.
 R_2 , X_2 and n_s are constant for I.M.

So only one parameter which control the torque is slip.

Mathematically for max. torque we can

write

$$\frac{dT}{ds} = 0.$$

$$\Rightarrow \frac{dT}{ds} = \frac{(K s E_2^2 R_2) \cdot \frac{d}{ds} (R_2^2 + s^2 X_2^2) - (R_2^2 + s^2 X_2^2) \cdot \frac{d}{ds} (K s E_2^2 R_2)}{R_2^2 + s^2 X_2^2} = 0$$

$$\Rightarrow K s E_2^2 R_2 (2s X_2^2) - (R_2^2 + s^2 X_2^2) (K E_2^2 R_2) = 0.$$

$$\Rightarrow 2K s^2 X_2^2 E_2^2 R_2 - R_2^2 K E_2^2 R_2 - K s^2 X_2^2 E_2^2 R_2 = 0.$$

$$\Rightarrow K s^2 X_2^2 E_2^2 R_2 - R_2^2 K E_2^2 R_2 = 0.$$

$$\Rightarrow K E_2^2 R_2 (s^2 X_2^2 - R_2^2) = 0.$$

$$\Rightarrow s^2 X_2^2 = R_2^2$$

$$\Rightarrow s^2 = \frac{R_2^2}{X_2^2}$$

$$\Rightarrow s = \frac{R_2}{X_2} \quad (\text{neglecting negative slip})$$

At max. torque, the slip is denoted as s_m .

$$\therefore \boxed{s_m = \frac{R_2}{X_2}} \rightarrow \text{this is the cond for max. torque.}$$

Magnitude of Max. Torque:-

max. torque is

$$T_M = \frac{K s_m E_2^2 R_2}{R_2^2 + (s_m X_2)^2}$$

Putting the value of $s_m = \frac{R_2}{X_2}$.

$$T_M = \frac{K \left(\frac{R_2}{X_2} \right) \cdot E_2^2 R_2}{R_2^2 + \left(\frac{R_2}{X_2} \cdot X_2 \right)^2}$$

$$\Rightarrow T_M = \frac{K E_2^2 \cdot R_2^2 \cdot \left(\frac{1}{X_2} \right)}{R_2^2 + R_2^2}$$

$$\Rightarrow T_M = \frac{K E_2^2 \cdot R_2^2 \cdot \left(\frac{1}{X_2} \right)}{2 R_2^2}$$

$$\Rightarrow \boxed{T_M = \frac{K E_2^2}{2 X_2}}$$

from the above expression, we can observed that

* max. torque is inversely proportional to rotor reactance

* It is directly proportional to induced emf at stand

* The most interesting observation is, "The max. torque is not depend on rotor resistance ' R_2 '." But the slip at which it occurs i.e. speed at which it occurs depends on the value of rotor resistance ' R_2 '.

Torque-Slip Characteristics:- (Squirrel-cage-rotor)

As the I.M. is loaded from no load to full load, its speed decreases, hence slip increases. Due to increased load, motor has to produce more torque to satisfy the load demand. The torque is depend upon the slip as explain earlier.

The curve plotting betⁿ ~~torque~~ torque against slip from $s=1$ to $s=0$ is called torque-slip characteristics.

We know that

$$T \propto \frac{SE_2^2 R_2}{R_2^2 + (sX_2)^2}$$


As supply voltage is constant, so E_2 also constant.

$$\therefore T \propto \frac{SR_2}{R_2^2 + (sX_2)^2}$$

Now to Judge the nature of torque-slip characteristics, Let us derive the

②

Slip range ($s=0$ to $s=1$) is to two parts and analyse them independently.



$s_m \rightarrow$ slip at max. Torque.

OA \rightarrow Stable region.

AB \rightarrow Unstable region.

i) low slip region:-

In low slip region, 's' is very small. Due to this $(sx_2)^2$ is also too small as compared to R_2^2 . So it can be neglected.

$$\text{So } T \propto \frac{sR_2}{R_2^2}$$



$$\Rightarrow \boxed{T \propto s}$$

(As R_2 is constant)

Hence in low slip region torque is directly proportional to slip.

So as load increases, speed decreases and slip increases, so torque increases.

Hence the graph is straight line in nature (line OA) which is called stable region.

ii) High-slip region:-

In this region slip is high i.e. slip value is approaching to 1.

Here we can assume that R_2^2 is very small as compared to $(sx_2)^2$.

$$\text{So } T \propto \frac{sR_2}{(sx_2)^2}$$


$$\Rightarrow T \propto \frac{sR_2}{s^2 x_2^2}$$

$$\Rightarrow \boxed{T \propto \frac{1}{s}} \quad (\text{As } R_2 \text{ \& } x_2 \text{ are constant})$$

So in high region torque is inversely proportional to slip. Hence its nature is like rectangular hyperbola (line AB). This region is also called unstable region.

- x -

Power-stages in an I.M:-



The three phase supply given to the stator is the net electrical input to the motor. This is nothing but the Stator Power (P_s). The part

of the power is utilised to supply the losses in the stator which are stator Cu. loss and stator iron loss.

The remaining power is delivered to the rotor magnetically through air-gap. is called rotor power (P_r).

$$\text{So } P_r = P_s - \text{stator loss (Core + Copper)}$$

The rotor is not able to convert its entire input to mechanical as it has self iron and copper loss. So rotor iron loss is very small as compared to copper loss. So iron loss is negligible. So only copper loss is there denoted as P_c .

$$\text{So Rotor Cu. loss } P_c = 3 \times I_{2r}^2 \times R_2 \rightarrow \text{for 3-phase}$$

↗ G. at running and?

After supplying these losses, the remaining part of ' P_r ' is converted into mechanical power developed by the motor denoted as (P_m). ~~Power~~

$$\text{So } P_m = P_r - P_c$$

Now this power, motor tries to deliver to the load connected to shaft. But during the mechanical transmission, the part of P_m is goes to losses due to friction and windage.

$$\text{So } P_{out} = P_m - \text{Mechanical losses}$$

↳ This power is the final output to the load.

So Rotor efficiency (η_r) = $\frac{\text{Rotor output}}{\text{Rotor input}} = \frac{P_m}{P_r}$.

and Net motor efficiency (η_m) = $\frac{\text{Motor output}}{\text{Motor input}} = \frac{P_{out}}{P_{in}} = \frac{P_{sh}}{P_s}$

Relation Betⁿ Rotor Input, Rotor output and Rotor Cu. loss
(P_r, P_m, P_c)

$P_r \rightarrow$ Rotor Input

$P_m \rightarrow$ Rotor output

$P_c \rightarrow$ Rotor Cu. loss.

Let T = Gross torque developed by motor

We know that

$$P = T \times \omega$$

$$\omega = \text{angular speed} = \frac{2\pi N_s}{60}$$

Now input to the rotor (P_r) is from stator side through rotating magnetic field which is rotating at synchronous speed (N_s).

$$\text{So } P_r = T \times \omega_s$$

$$\Rightarrow P_r = T \times \frac{2\pi N_s}{60} \quad \text{--- (1)}$$

Rotor tries to deliver this torque to the load. so rotor output is gross mechanical power (P_m). and torque ' T '.

(16)

$$\text{So } P_M = T \times \omega_r \quad (\text{Here } \omega_r \neq \omega_s)$$

$$\Rightarrow P_M = T \times \frac{2\pi N_r}{60} \quad \text{————— (2)}$$

The difference betⁿ P_r and P_M is rotor Cu. loss (P_c)

$$\text{So } P_c = P_r - P_M$$

$$= \left(T \times \frac{2\pi N_s}{60} \right) - \left(T \times \frac{2\pi N_r}{60} \right)$$

$$\Rightarrow P_c = T \times \frac{2\pi}{60} (N_s - N_r) \quad \text{————— (3) } /$$

Now dividing eqⁿ (3) by eqⁿ (1)

$$\text{So } \frac{P_c}{P_r} = \frac{T \times \frac{2\pi}{60} (N_s - N_r)}{T \times \frac{2\pi N_s}{60}}$$

$$\Rightarrow \frac{P_c}{P_r} = \frac{N_s - N_r}{N_s} = s.$$

$$\Rightarrow \frac{P_c}{P_r} = s$$

$$\Rightarrow \boxed{\text{Rotor Cu. loss } (P_c) = s \times \text{Rotor input } (P_r)}$$

————— (4)

$$\text{Now } P_r - P_c = P_M$$

$$\Rightarrow P_r - s P_r = P_M$$

$$\Rightarrow P_r (1 - s) = P_M$$

$$\Rightarrow \boxed{\frac{P_M}{P_r} = (1 - s)} \quad \text{————— (5)}$$

So from eqn (4) and (5), the relationship can be expressed in form of ratio is

$$P_r : P_c : P_m = 1 : S : 1 - S$$

$$\frac{P_c}{P_m} = \frac{S}{1 - S}$$

$$\frac{P_r}{P_c} = \frac{1}{S}$$

$$\frac{P_r}{P_m} = \frac{1}{1 - S}$$

— X —

Torque Ratio:-

The performance of the motor is sometimes expressed in terms of comparison of various torque.

i) Full load and max. Torque Ratio:-

In general

$$T \propto \frac{S E_2^2 R_2}{R_2^2 + (S X_2)^2}$$

Let S_f = full load slip

& S_m = slip for max. torque T_m

$$\therefore T_{f.L.} \propto \frac{S_f E_2^2 R_2}{R_2^2 + (S_f X_2)^2}$$

$$\& T_m \propto \frac{S_m E_2^2 R_2}{R_2^2 + (S_m X_2)^2}$$

$$\therefore \frac{T_{f.L.}}{T_m} = \frac{S_f E_2^2 R_2}{R_2^2 + (S_f X_2)^2} \times \frac{R_2^2 + (S_m X_2)^2}{S_m E_2^2 R_2}$$

$$\Rightarrow \frac{T_{f.L.}}{T_m} = \frac{S_f}{S_m} \times \frac{R_2^2 + (S_m X_2)^2}{R_2^2 + (S_f X_2)^2}$$

Dividing both numerators and denominators by X_2^2

$$\frac{T_{f.L.}}{T_m} = \frac{S_f}{S_m} \times \frac{\left(\frac{R_2^2}{X_2^2} + S_m^2 \right)}{\left(\frac{R_2^2}{X_2^2} + S_f^2 \right)}$$

$$= \frac{S_f \times 2 S_m^2}{S_m \times (S_m^2 + S_f^2)} \Rightarrow$$

$$\boxed{\frac{T_{f.L.}}{T_m} = \frac{2 S_f S_m}{(S_m^2 + S_f^2)}}$$

ii) Starting Torque & maximum Torque:-

We know that-

$$T_{st} = \frac{E_2^2 R_2}{R_2^2 + X_2^2}$$

While for T_m , $s = s_m$

$$\therefore T_m = \frac{s_m E_2^2 R_2}{R_2^2 + (s_m X_2)^2}$$

$$\therefore \frac{T_{st}}{T_m} = \frac{E_2^2 R_2}{R_2^2 + X_2^2} \times \frac{R_2^2 + (s_m X_2)^2}{s_m E_2^2 R_2}$$

$$= \frac{R_2^2 + (s_m X_2)^2}{s_m [R_2^2 + X_2^2]}$$

Dividing both numerator & denominator by X_2^2 , we get

$$\therefore \frac{T_{st}}{T_m} = \frac{\left(\frac{R_2^2}{X_2^2} + s_m \right)}{s_m \left(\frac{R_2^2}{X_2^2} + 1 \right)}$$

$$\Rightarrow \frac{T_{st}}{T_m} = \frac{2s_m^2}{s_m(1+s_m^2)} = \frac{2s_m}{1+s_m^2}$$

$$\Rightarrow \boxed{\frac{T_{st}}{T_m} = \frac{2s_m}{1+s_m^2}}$$

iii) Starting Torque and f.l. Torque:-

We know that

$$T_{st} = \frac{E_2^2 R_2}{R_2^2 + X_2^2}$$

and full load torque

$$T_{f.L} = \frac{S_f E_2^2 R_2}{R_2^2 + (S_f X_2)^2} \quad \text{at } s = S_f$$

$$\therefore \frac{T_{st}}{T_{fL}} = \frac{E_2^2 R_2}{R_2^2 + X_2^2} \times \frac{R_2^2 + (S_f X_2)^2}{S_f E_2^2 R_2}$$

$$= \frac{R_2^2 + (S_f X_2)^2}{S_f (R_2^2 + X_2^2)}$$

Dividing both numerator and denominator by X_2^2

$$\therefore \frac{T_{st}}{T_{fL}} = \frac{\frac{R_2^2}{X_2^2} + S_f^2}{S_f \left(\frac{R_2^2}{X_2^2} + 1 \right)}$$

$$\Rightarrow \boxed{\frac{T_{st}}{T_{fL}} = \frac{S_m^2 + S_f^2}{S_f (S_m + 1)}}$$

Problem:-

On a 4 Pole, 3- ϕ , 50Hz induction motor
Calculate, the frequency of the rotor current

i) at standstill.

ii) motor is running at 500 rpm in same direction as field.

iii) motor is running at 500 rpm in opposite direction as field.

iv) motor is running at 2000 rpm in same direction as field.

Solu:- We know that

$$N_s = \frac{120f}{P} = \frac{120 \times 50}{4} = 1500 \text{ rpm.}$$

i) At standstill:-

$$N_r = 0$$

$$\text{Here slip} = \frac{N_s - N_r}{N_s} = \frac{N_s - 0}{N_s} = 1$$

$$\therefore \text{Rotor frequency } f_r = Sf = 1 \times 50 \text{ Hz} = 50 \text{ Hz.}$$

ii) Motor runs at 500 rpm as the same direction of field.

$$\text{Here slip } S = \frac{1500 - 500}{1500} = \frac{1000}{1500} = 0.66 \text{ motoring operation.}$$

$$\therefore \text{Rotor frequency } f_r = Sf = 0.66 \times 50 = 33.33 \text{ Hz}$$

iii) Motor runs at 500 rpm but in opposite direction

$$\text{Here slip } S = \frac{1500 - (-500)}{1500} = \frac{2000}{1500} = 1.33 \text{ Breaking operation}$$

(21)


iv) Motor runs at 2000 rpm in same direction

$$N_s = 1500 \text{ rpm.}$$

$$N_r = 2000 \text{ rpm.}$$

$$\text{Here slip} = \frac{N_s - N_r}{N_s} = \frac{1500 - 2000}{1500} = \frac{-0.33}{\text{Generating mode.}}$$

$$\therefore f_r = S f = -0.33 \times 50 = -16.66 \text{ Hz.}$$



Method of Starting of I.M.

22

Necessity of Starter :-

In a 3- ϕ I.M., the magnitude of an induced emf in the rotor ckt depends on slip, and this induced emf effectively decides the magnitude of the rotor current.

$$I_{20} = \frac{SE_2}{\sqrt{R_2^2 + (Sx_2)^2}}$$

But at start, slip is ~~zero~~^{max.}, so induced emf is very large, so the current also. and this current is 5 to 8 times the full load current which may damage the motor winding. Like short ckt condition of X^r .


So to reduce the induced emf Starter is used. Similarly such sudden inrush current causes large line voltage drop. Thus other appliances connected to the same line may affect their working.

Types of Starter :-

The various types of starters are

- i) Stator resistance starter.
- ii) Auto transformer starter.
- iii) Star-Delta Starter.
- iv) Rotor resistance starter.
- v) Direct on line starter.

1) Stator Resistance Starter :-




In order to apply the reduced voltage to the motor, three resistances are added in series with each phase of stator winding. Initially the resistances are kept maximum. Due to this large voltage will drop across the resistance. Hence it reduces the high starting current.

When the motor starts running the resistances are gradually cut-off from the ~~stator~~ stator circuit. When it is entirely removed, then rated voltage will be applied to stator and motor runs at normal speed.

The starter is simple in construction and cheap. It can be used for both star or delta ~~stator~~ stator. But there are large power losses due to resistances.

ii) Auto-transformer starter :




A three phase star connected auto transformer can be used to reduce the voltage applied to the stator.

It consists of a suitable change over switch. When the switch is in start position, the stator winding is supplied with reduced voltage. This can be controlled by tapings provided with a auto transformer. When the motor gathers 80% of the normal speed, the change over switch is thrown in to run position and the motor runs with rated voltage at normal speed. Changing of switch is done automatically by using relay.

In this type power loss is very less at starting. It can be used for both star or Delta connected stator wdg. But it is expensive than stator resistance starter.

iii) Star-Delta Starter:-




This is the cheapest starter of all and hence used very commonly for I.M. It uses Triple pole Double throw ~~TP~~ (TPDT) switch. The switch connects the stator wdg in star at start. Hence per phase voltage get reduced by the factor $\frac{1}{\sqrt{3}}$. Due to this reduced voltage starting current is limited.

When the switch is thrown to other side the wdg get connected in delta. so it sets normal rated voltage. The wdg are connected in delta when motor gathers sufficient speed.

The cheapest of all and maintenance free operation are two important ~~adv~~ advantages of this starter.

iv) Rotor Resistance Starter:-




To limit the rotor current which consequently reduces the current drawn by the motor from the supply, the resistance can be inserted in the rotor ckt at start.

The external resistance is inserted in each phase of rotor wdg through slip ring. Initially max. resistance is in the ckt. As motor gathers speed, the resistance is gradually cut-off.

The main advantage is it limits the current at starting and as the rotor resistance increases, the starting torque also increases. Its main disadvantage is it is only used in slip ring induction motor.

✓) Direct on line Starter (D.O.L)



in case of small capacity motor having rating less than 5 HP, the starting current is not very high and such motor can withstand such starting current. Such motor use a type of starter which is used to connect stator directly to the supply without any reduction in voltage. Hence the starter is known as Direct On line starter.

It is used because it protects the motor from various severe abnormal conditions like over loading, low voltage, single phasing etc.

The NO Contact is normally open & NC is normally closed. At start, NO is pushed for friction of second due to which coil gets energized and attracts the contactor.

So starter get directly supply. The additional contact provided, ensure that as long as supply is ON, the coil sets supply and keeps contact in ON position. When NC is pressed, the coil get opened due to which coil get de-energized and motor gets switched off from the supply.

-X-

Speed Control:-

A 3-phase I.M. is practically a constant speed motor like a d.c. shunt motor. But in case of 3- ϕ I.M. is very difficult to ~~find~~ achieve smooth speed control.

We know that

$$N_r = N_s (1-s)$$

from this expression, it can be seen that, the speed of I.M. can be changed either by changing synchronous speed (N_s) or by changing slip (s).

Similarly

$$T \propto \frac{s E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

So as the parameter like R_2 , E_2 are changed, then keep the torque constant for constant load condition.

Thus speed of the I.M. can be controlled by basically two methods.

- i) from stator side
- ii) from rotor side.

from stator side. it includes following method.

- ✓ i) Supply frequency control, called V/f control
- ✓ ii) Supply voltage control.
- ✓ iii) Controlling number of stator poles
- iv) Adding Rheostats in stator ckt.

from Rotor side, it includes

- ✓ i) Adding external resistance in rotor ckt.
- ii) Cascade control
- iii) Injecting slip frequency voltage into rotor ckt.

i) Supply frequency control or V/f control:-

The Synchronous Speed is given by

$$N_s = \frac{120f}{P}$$

Thus by controlling the supply frequency smoothly, the synchronous speed can be controlled over a wide range. This gives smooth speed control of an I.M.

But the expression for the air gap flux is

$$\phi_g = \frac{1}{4.44 K_1 T_{ph1}} \left(\frac{V}{f} \right)$$

This is according to emf eqn of α^r .

Where

K_1 = Stator wdg constant.


T_{ph1} = Stator turns per phase

V = Supply voltage


f = Supply frequency.

It can be seen that if the frequency changed, the air gap flux also gets affected. This may result in to Saturation of ~~the~~ Stator and rotor cores. Such Saturation leads to the sharp increase in the no load current of the motor. Hence it is necessary to maintain air gap flux constant when supply frequency changes.

To achieve this, we have to keep V/f ratio constant. Hence in this method, the supply to the I.M. require variable voltage, variable frequency supply and can be achieved by a electronic ~~scheme~~ scheme by using converter and inverter ext.



(Electronic scheme for V/f control)



[Torque-slip characteristics with variable f & constant (V/f)]

Its main disadvantages of this method is that, the supply obtained can not be used for other device. Hence a individual scheme for a separate motor is required which makes it costly.

ii) Supply voltage control:-

We know that

$$T \propto \frac{SE_2^2 R_2}{R_2^2 + (sx_2)^2}$$

Now E_2 , the rotor induced emf at stand still depends on the supply voltage 'V'.

$$E_2 \propto V$$

and we know that, at low slip region

$$T \propto sV^2 \text{ (for constant } R_2 \text{)}$$

Now if supply voltage is reduced below rated value, the torque also decreases. But to supply the same load, it is necessary to produce same torque, hence value of slip must be increased. To slip increase, motor reacts by running a lower speed, to decrease the supply voltage.

But in this method, due to reduction in voltage, current drawn by motor increases. Large change in voltage for small change in speed is required is the biggest disadvantages, so it is rarely used only for motor driving fan load type.

iii) Controlling Number of Poles:-

(27)

In this method, instead of one wdg, two separate stator wdg are placed in stator core. The wdg are placed in stator ~~core~~ slots only but are electrically isolated from each other. Each wdg is divided in to coils to which pole changing with consequent poles, facility is provided.

By using switching arrangement two speed can be achieved. The various limitation of this method are

i) It is applied only for squirrel cage I.M.

ii) Smooth speed control is not possible.

iii) Two different stator wdg is required which increases the cost of motor.

iv) Complicated from the design point of view.

iv) Adding External resistance to Rotor ckt:-

We know that

$$T \propto \frac{SE_2^2 R_2}{R_2^2 + (SX_2)^2}$$

for low slip region, $(SX_2)^2 \ll R_2$, and can neglected. So

$$T \propto \frac{SR_2}{(R_2)^2} \Rightarrow T \propto \frac{S}{R_2}$$

Thus if the rotor resistance is increased, the torque produced decreases. But when the load of the motor is same, motor has to supply same torque. So motor reacts by increasing its slip to compensate decrease in torque due to R_2

So due to additional rotor resistance, speed of motor decreases. Thus by increasing rotor resistance R_2 speed below the normal value can be achieved and also starting torque will increase.

But its limitations are

- i) Large speed change are not possible due to large cu. loss in rotor.
- ii) It is only used for slip ring I.M.
- iii) Speed above the normal speed can not be obtained.
- iv) due to large power loss, efficiency is low.

- x -

Enclosures and plugging - of I.M :-

Motor enclosures not only holds the motor component but also protects the internal components from moisture and contaminants. The degree of protection depends on the enclosure type. In addition, the type of enclosure affects the motor cooling. There are two categories of enclosures.

i) open type.

ii) Totally enclosed type.

i) Open type Enclosures:-

Open enclosures permit cooling air to flow through the motor. Fan blades are attached to the rotor and move air to the motor. This type of enclosure should be used in environments free from contaminants.

ii) Totally enclosed type:-

In some applications, the air surrounding the motor contains a corrosive or harmful element which can damage the internal parts of the motor. Totally enclosed type limits the flow of air into the motor, but is not airtight. However, a seal at the point where the shaft passes through the housing prevents water, dust, and other foreign matter from entering the motor along the shaft.

Plugging of An Induction motor:-


In some industrial application, it is desired to bring the running induction motor to a rapid stop. This can be done by simply interchanging the two stator leads. This process is called Plugging.

When we interchange two stator leads the revolving field ~~reverses~~ suddenly turns in the opposite direction to the rotor. During the plugging period, the motor acts as a brake. The mechanical power associated with the rotor is entirely dissipated as heat in the rotor. Consequently plugging produces I^2R losses in the rotor.

Induction Generator:-


When the slip of the induction motor is negative, i.e. when the I.M. runs faster than the synchronous speed, the I.M. runs as a generator called Induction Generator.

Thus torque and power in this case will be negative.



on this fig. the I.M. is shown which is driven by a motor like Petrol engine. The motor is supplied with electrical power from 3-phase line. When the motor speed exceeds the synchronous speed the active power is delivered by the motor and the corresponding mode of operation of motor is called generating mode.

The induction generator is not self exciting in the sense that supply must be maintained to act as a generator. Thus it must be operated with other generators which supply exciting current of fixed frequency which is required for the production of rotating magnetic field. Thus it takes reactive power from the line to create the magnetic field.



Single Phase-Induction Motor.

①

Single Phase I.M. are usually used in domestic purpose. Some of them are even fractional horse power rating, which are used in application like small toys, small fans, hair dryers etc.

Construction:

Similar to d.c. motor, 1- ϕ I.M has basically two main parts. The stationary part is stator while rotating part is rotor.


The stator is laminated construction made up of stampings. The stampings are slotted in its periphery to carry the stator winding or main wdg. This is excited by single phase a.c. supply. The stator wdg is wound for certain definite number of poles means when excited by single phase a.c. supply, stator produces the magnetic field which creates the effect of certain definite number of poles. The synchronous speed is denoted as N_s and is given by

$$N_s = \frac{120f}{P} \text{ r.p.m.}$$

The induction motor never rotates with the synchronous speed but rotates at a speed of slightly less than synchronous speed.

The Rotor construction is ~~same~~

Squirrel-cage type which consists of uninsulated copper or aluminium bars.





Working Principle:-

For Motoring action, there must exist two fluxes which interact with each other to produce the torque. In d.c. motor field wdg produce the main flux ~~while~~ while d.c. supply gives to armature to produce armature flux. The main flux and armature flux interact to produce the torque.

But in $1-\phi$ I.M. single phase supply is given to the stator wdg. The stator wdg carries an alternating current which produce a flux is also alternating in nature. But $1-\phi$ I.M. is not self starting. Let us see why & it is not self starting with the help of a theory called double revolving field theory.

Double Revolving Field Theory:-



(2)

"According to this theory, any alternating quantity can be resolved into two rotating component which rotate in opposite direction and each having magnitude as half of the max. magnitude of the alternating quantity."

On case of ϕ_{Im} I.M. the stator ~~and~~ produces an alternating magnetic field having max. magnitude of ϕ_{Im} . So according to double ~~field~~ Revolving field theory, consider two component having magnitude $\phi_{Im}/2$, rotating in opposite direction at a synchronous speed 'N's.

Let $\phi_f \rightarrow$ forward component rotating in anticlockwise direction.

$\phi_b \rightarrow$ Backward component rotating in clockwise direction.

The resultant of these two is the original stator flux.


At start both the components are shown opposite to each other. Thus the resultant flux $\phi_R = 0$. This is nothing but the instantaneous value of stator flux at start. After 90° as shown in fig(b), both the fluxes pointing in same direction. Hence Resultant ϕ_R is the algebraic sum of the magnitude of two component.

$$\text{So } \phi_R = \left(\frac{\phi_{Im}}{2} + \frac{\phi_{Im}}{2} \right) = \phi_{Im}.$$

This is nothing but the instantaneous value of stator flux at $\theta = 90^\circ$. Thus continuous rotation of two component gives the original alternating stator flux.

Both the components are rotating and hence cut by the rotor conductors. Due to this emf gets induced in rotor which circulates rotor current. The rotor current produces a rotor flux. This flux interacts with forward component ϕ_f to produce a torque in one particular direction say anticlockwise direction, while rotor flux interacts with backward component ϕ_b to produce a torque in the clockwise direction. If anticlockwise torque is +ve then clockwise torque is negative.

At start these two torque are equal in magnitude but opposite in direction. Each torque tries to rotate the rotor in its own direction. So net torque is zero.



So ~~not~~ 1- ϕ I.M. is not self

Starting.




- x -

Types of 1- ϕ I.M.

In practice some arrangement is provided in the single-phase I.M. so that the stator flux produced becomes rotating type rather than alternating type, which rotates in one particular direction only. Thus depending upon the methods of producing rotating stator magnetic flux, the single phase i.m. are classified as

- i) Split Phase I.M.
- ii) Capacitor Start Capacitor Run I.M.
- iii) Shaded Pole I.M.

i) Split Phase I.M.:-




This type of motor has 1- ϕ stator wdg called main winding, in addition to this stator carries one more winding called auxiliary wdg or starting wdg. The auxiliary winding carries a series resistor such that its impedance is highly resistive in nature. But the main winding is inductive in nature.

Let I_m = Current through main wdg
 I_{st} = Current through auxiliary wdg.

As main wdg is inductive, current I_m lags voltage 'V' by a large angle ' ϕ_m ' while I_{st} is almost in phase in 'V' as it is highly resistive. Thus there exist a phase difference of ' α ' betn the two current and hence the two flux. Due to this, starting torque, which acts only in one direction is produced.

When motor gathers a speed up to 75% to 80% of synchronous speed, centrifugal switch get opened mechanically and in running condition auxiliary wdg remains out of the ckt. So motor runs only main wdg.

As the current I_m and I_{st} are splitted from each other by angle ' α ' at start, the motor is commonly called split phase motor.




The starting torque T_{st} is proportional to the split angle ' α ' but split phase motor has poor starting torque.

The direction of rotation can be reversed by reversing the terminals of either ~~the~~ main or auxiliary wdg.


Application:-

As it has low starting torque, so these are used for low load like fans, blowers, grinder, centrifugal pump, washing machine, office equipment. These are available in the range of 1/20 to 1/2 kw.

Capacitor ~~Start~~ Capacitor Run Induction motor:-



The construction of this type motor is similar to the resistance split phase type. The only difference is that in series with auxiliary wdg the capacitor is connected.



(Phasor diagram)

Depending upon the capacitor in ckt permanently or is disconnected from the ckt using centrifugal switch, these motors are classified as


- i) Capacitor start motor
- ii) Capacitor start Capacitor run motor.

In Capacitor start motor, the capacitive ckt draws a leading current, this feature used in this type of motor to increase the split phase angle α between


two current I_m and I_{st} . The starting torque is proportional to α' and hence such motor produce very high starting torque.

When speed approaches to 75 to 80% of synchronous speed, the starting wdg get disconnected due to operation of centrifugal switch.

But in case of capacitor start, Capacitor run motor, there is no centrifugal switch and capacitors remain permanently in the ckt. This improves the power factor.



The phasor diagram is same as before. The performance not only at start but in running condition also depends on capacitor 'C' hence its value is to be designed so as to conform to best starting and best running cond'. So starting torque available in such type of motor is about 50 to 100% of full load torque.





Application:-


As these motor have high starting torque hence used in compressors, conveyors, grinder, fan, refrigerators, air conditioner etc.

(5)

Shaded Pole Induction Motor.




This type of motor consists of squirrel cage rotor and stator consists of salient pole i.e. projected poles. The poles are shaded i.e. each pole carries a copper band one of its unequally divided parts called shading band.



When 1- ϕ a.c. supply is given to the stator wdg, due to shading provided to the poles a rotating magnetic field is generated.

The current carried by the stator wdg is alternating and produces alternating flux. The distribution of this flux in the pole area is greatly influenced by the role of copper shading band. Consider the three instants t_1 , t_2 & t_3 during first half cycle of flux.

At instant $t = t_1$, rate of rise of current and hence the flux is very high. Due to the $\times r$ action large emf gets induced in the copper shading band. This producing its own flux. According to lenz's law, the direction of this current is so as to oppose the cause i.e. rise in current. Hence shading rings flux is opposes the main flux. Hence there is crowding of flux in non shaded part while weakening of flux in shaded part. overall magnetic axis shifts in non-shaded part as shown in fig(a)




At instant $t = t_2$, rate of rise of current and hence, the rate of change of flux is zero as flux almost reaches to its max. value. So $\frac{d\phi}{dt} = 0$. Hence there is very little induced emf in the shading ring. Hence shading ring flux is also negligible, hardly affecting the distribution of the main flux. Hence the main flux distribution is uniform and magnetic axis lies at the center of the pole face as shown above (fig-b)

At instant $t = t_3$, the current and the flux is decreasing. The rate of decrease is high which again induces a very large

(6)

ent in the shading ring which produces its own flux. Now direction of the flux produced by the shaded ring ~~which produces its own flux, whose direction of the~~ ~~flux produced by the shaded ring~~ oppose the cause which is decrease the flux. So it oppose the decrease in flux means its direction is same as that of main flux, strengthening it. So there is crowding of flux in the shaded part as compared to non-shaded part. Due to this the magnetic axis shifts to the middle of the shaded part of the pole. This is shown in fig-(c).

This sequence keeps on repeating for negative half cycle too. Consequently this produces an effect of rotating magnetic field. Due to this motor produces the starting torque. The starting torque is low which is about 40 to 50% of f.l. torque.



Due to absence of centrifugal switch the construction is simple and robust, but there is some limitation.

1. Low Power factor.
2. Due to I^2R , copper loss in shading ring is high.
3. Speed reversal is very difficult. To achieve this the additional set of shading ring is required.

in the size and power rating of these motors is very small. These motors are usually in the range of $1/300$ to $1/20$ kW.

Application:-

Small fans, toy motors, advertising displays, film projector, record players, gramophones, hair driers, photo copying machine etc.

- * For Permanent Capacitor Motor \rightarrow Paper Capacitor
- * For Capacitor Start, Capacitor run motor \rightarrow Start-Electrolytic Capacitor
Run-Paper Capacitor

Commutator Motor.


Single Phase Series Motor

or

Universal Motor.

A d.c. series motor will rotate in the same direction ~~and~~ regardless of the polarity of the supply. A d.c. series motor also operates on A.C. supply, then it is called A.C. series motor. But some changes will be required. These are.

- i) The entire magnetic ckt is laminated in order to reduce the eddy current loss. Hence A.C. series motors are more expensive.
- ii) The series field wdg uses as few turns as possible to reduce the reactance of the field wdg. This reduces the voltage drop across field.
- iii) A high field flux is obtained by using a low reluctance magnetic ckt.
- iv) To reduce the sparking at commutator a high resistance leads are connected to the commutator segment.



Construction:-

The construction of A.C. series motor is very much similar to d.c. series motor except the above changes. Such motor can operate both A.C. & d.c. and resulting torque-speed characteristics about the same. Hence such motor is also called universal motor.

Operation:-

When motor is connected to A.C. supply, the same alternating current flows through the field & armature windings. The field winding produces an alternating flux that reacts with the current flowing in the armature to produce a torque. It may be noted that no rotating flux is produced in this type of machine. The principle of operation is same as d.c. series motor.

Characteristics:-

- i) The speed increases to a high value with a decrease in load.
- ii) It has high starting torque.
- iii) At full load, p.f. is about 90%.

Application:-

- i) high speed vacuum cleaner
- ii) sewing machines
- iii) electric shavers
- iv) drills
- v) m/c tools etc


Repulsion Motor:-

Repulsion motor are 1- ϕ commutator motor, and are following three types.

- i) Plain repulsion motor.
- ii) Repulsion start Induction motor.
- iii) Repulsion Induction motor.

i) Plain Repulsion motor:-

A repulsion motor is similar to A.C. Series motor except that, the brushes are not connected to supply but are short circuited and the field structure are non-salient pole type.



Construction:-

The field of stator wdg is wound like the main wdg of a Split-Phase motor and is connected directly to 1- ϕ supply. The short-circuited brushes effectively forces rotor in to a type of squirrel cage.

The major difficulties with an ordinary single-phase I.M. is low starting torque. By using a commutator motor with brushes short ckted, it is possible


to vary the starting torque by changing the brush axis.

Principle of operation:-

fig. shows the schematic diagram of Repulsion motor.

Now consider two pole repulsion motor with brushes placed at right angle to the main field pole (i.e. Stator)

When a 1- ϕ a.c. is fed to Stator $\&$, an alternating field will be produced. Let at this particular moment, the alternating c.t. is passing through its $\&$ ve half $\&$ increasing in magnitude. So it will set up a magnetic flux of increasing nature which acts from north to South. This increasing flux will produce an e.m.f. in the armature $\&$ set up a flux in opposite direction to stator flux, according to Lenz's law. As both the fluxes are opposite to each other and equal in magnitude, so no torque will develop.



(3)

If now the brushes are placed midway betⁿ the field poles. which is made for the same moment of time as in the previous case, a clockwise ct. will flow through the brushes in the upper half of armature ~~way~~ way and anti-clockwise in lower half of the way. This current will produce equal & opposite torque, so rotor will not rotate.

Now Suppose, the brushes are placed at a particular angle ' α ' to the field axis. At this position the main field flux & armature induced flux is in same direction. so net torque will be in one direction & motor will rotate.

Since the rotor of this motor possesses high resistance due to d.c. armature way, its starting current is low. However it has high starting torque & therefore started on load. Therefore it is used in lifts, cranes etc.

- X -

ii) Repulsion Start, Induction Motor:

The construction of this motor is similar to an ordinary repulsion motor but an arrangement is provided in its rotor so that, the commutator segments are short circuited after the motor speeds up. For this purpose a spring type centrifugal device is ~~provided~~ fitted inside the commutator segments.

When a c 1- ϕ supply is fed to the stator wdg, the motor starts as a plain repulsion motor, giving high starting torque. When the speed reaches a pre-determined value, the spring of the centrifugal device expands, & short circuits all commutator segments and the motor operates as an ordinary induction motor. Hence the motor is named so.

This motor is used at such places, where it is required to have high starting torque & constant speed as in lathes, sawmills, water pumps etc.

(iii) Repulsion Induction Motor:-

The Stator of the Repulsion induction motor has only one winding but the rotor has two distinct wdg such as commutator wdg, similar to d.c. armature & a low resistance & high reactance squirrel cage winding. The ^{two} windings are housed in separate slots as in the case of double squirrel cage I.M. The armature wdg is done in upper slots and its connection are brought to the commutator segments. The squirrel cage wdg is made of copper bars and is placed deep in slots which are short circuited by copper rings.

At the time of starting, the squirrel cage wdg will be practically ineffective due to high frequency of the induced e.m.f. & hence have high reactance. Therefore motor starts as a repulsion motor giving high starting torque. As the motor speeds up, the frequency of the rotor current lowers down & thus reducing the reactance of squirrel cage & now the squirrel cage wdg becomes effective in producing torque.

This motor is also a constant speed motor, having high starting torque. Thus it is suitable for machine tools, pumps, blowers, mixing machines etc.

Special Electrical Machine.

①


Principle:-

Stepper motors are also known as Stepping motors or step motor. A stepper motor is an electromagnetic motor, that rotates by a specific number of degree in response to an input electrical signal. Typical step size are 2° , 2.5° , 7.5° & 15° for each electrical pulse. Note that there is no continuous energy conversion, so that rotor does not rotate continuously.


Stepper motors are ~~two~~ ^{three} types

- i) Permanent-magnet (PM) Stepper motor.
- ii) Variable-Reluctance (VR) Stepper motor.
- iii) Hybrid Stepper motor.


i) Permanent-Magnet Stepper motor:-



(Fig-1)



(Fig-2)



(Fig-3)

Construction:-

The stator of a PM stepper motor is composed of steel lamination and carries stator winding. The stator winding is energized from a d.c. source to create two or more stator poles. The rotor of the motor is a permanent magnet, made of high-retentivity steel alloy. The rotor has even no. of poles.

Operation:-

For this stepper motor as shown in fig. no. of rotor poles $N_r = 2$, & no. of phases $m = 2$.

$$\therefore \text{Step angle, } \alpha = \frac{360^\circ}{m N_r} = \frac{360^\circ}{2 \times 2} = 90^\circ / \text{step}.$$

→ When only Phase-A winding is excited by a constant c.t. (fig-i), stator tooth '1' becomes South pole & tooth-3 becomes North Pole. This makes the North Pole & South Pole of rotor align with stator as shown in fig-(i). The rotor will remain locked in this position as long as Phase-A is energized.

→ If Phase-A is de-energized, & Phase-B is energized as shown in fig-(ii), stator tooth becomes South Pole. As a result, North Pole of rotor align with South Pole of ^{stator} ~~rotor~~. Thus the rotor is displaced 90° in the anticlockwise direction.

(2)



→ If Phase-B is de-energized & Phase-A is excited with reverse current as shown in fig-(ii) i.e. opposite to case-1. The rotor will further rotate 90° in anticlockwise direction. Now the north pole of PM motor align with the stator tooth 3.

This is the way in which P.M. Stepper motor rotate.

ii) Variable Reluctance (VR) Stepper motor:

The VR Stepper motor operate on the same principle as the reluctance motor that is, when a piece of ferromagnetic material free to rotate, is placed in a magnetic field, torque acts on the material to bring it to the position of minimum reluctance to the path of magnetic flux.

Construction:-



The stator construction of a VR stepper motor is the same as that of a PM stepper motor. The rotor is made of soft steel with teeth & slots. For this VR stepper motor as shown in fig.

$$\begin{aligned}\text{Step angle, } \alpha &= \frac{N_s - N_r}{N_s N_r} \times 360^\circ \\ &= \frac{6 - 4}{6 \times 4} \times 360^\circ = 30^\circ / \text{step}.\end{aligned}$$

Operation :-

When the phase A is energized, the rotor teeth will align with the energized stator poles.

→ fig-(i) shows the location of the rotor when Phase-A is energized with a constant current. As long as Phase-A is energized, the rotor will be held stationary. Note that in this condition, the rotor teeth 1 & 2 are aligned with the energized stator teeth 1 & 4. The step angle $\alpha = 0^\circ$

→ When phase A is switched off & Phase-B is energized, the rotor will turn 30° clockwise so that the rotor teeth 3 & 4 align with the energized stator teeth 6 & 3. as shown in fig-(2)

→ The effect of de-energizing phase 'B' and energizing phase 'C' as shown in fig-(3). In this circuit, the rotor has further moved 30° clockwise, so that the rotor teeth 1 & 2 align with energized stator teeth 2 & 5.

→ After the rotor has displaced 60° from its starting point, the step sequence completed

(3)

one cycle.

The direction of rotation will be reversed if the switching sequence is in the order of A, C & B.

iii) Hybrid Stepper Motor:-

As the name, hybrid mean mixed. i.e. it combines the feature of the PM & VR stepper motor. The torque developed by this motor is greater than that of PM & VR type.

Construction:-





fig. shows the basic construction of hybrid stepper motor. The stator construction is similar to that of a VR & PM motor. The rotor of the hybrid stepper motor consists of two identical stacks of soft iron as well as permanent magnet as shown in fig-(ii).

Operation:-

The operating mode of the hybrid stepper motor is very similar to that of a PM & VR stepper motor. The phase ~~ways~~ are energized in proper sequence & the rotor rotates in step. The step angle, $\alpha = \frac{90^\circ}{N_r}$ in degree.

It may be noted that a hybrid stepper motor operates under the combined principle of the permanent magnet & variable reluctance stepper motor. Therefore the hybrid stepper motor develops both excitation torque & reluctance torque. Consequently, the resultant torque developed by the hybrid stepper motor is greater than that of the PM & VR stepper motor.

Application of Stepper motor:-

The stepper motor is used where step angle is required. like.

- i) moving the arm of robot.
- ii) Paper mill
- iii) Rolling mill
- iv) Packing industry.
- v) Clock. etc.



vii) Bushing:-

Forcelain bushings are cleaned & examined for cracks and chips. very slight chips may be ignored but any serious damage will require replacement.

The other maintenance procedures

- are
- viii) oil sampling.
 - ix) oil testing.
 - x) oil treatment.
 - xi) Paint work.
 - xii) Internal inspection.
 - xiii) opening of x^r.
 - xiv) Removal of cover.
 - xv) cores & coil.
 - xvi) Inspection.
 - xvii) Retanking.